POOR LI	EGIBILIT	Y	
PAGES IN THIS DO JE TO THE QUAL			READ
		•	
	C		
		,	
			•
		·	

SFUND RECORDS CTR 2178604



CH2M HILL

155 Grand Avenue, Suite 1000

Oakland, CA 94612

P.O. Box 12681

Oakland, CA 94604-2681

Tel 510.251.2426

Fax 510.893.8205

October 15, 2008 264204.PC.80/MIPC.C220H

Mr. Henry Chui California Environmental Protection Agency Department of Toxic Substances Control 700 Heinz Avenue, Suite 200 Berkeley, CA 94710-2721

Subject: Site Characterization and Cleanup Action Summary Report for Polychlorinated

Biphenyl Sites Building 116 AL#01 and AL#02, Investigation Area C2, Lennar

Mare Island, Vallejo, California

Dear Mr. Chui:

Enclosed are two copies of the Site Characterization and Cleanup Action Summary Report for Polychlorinated Biphenyl Sites Building 116 AL#01 and AL#02, Investigation Area C2, for Mare Island, Vallejo, California.

This document was prepared by Lennar Mare Island, LLC (LMI) as part of the scope of the Environmental Services Cooperative Agreement to complete remaining environmental work at Mare Island, and in accordance with the Consent Agreement between LMI, City of Vallejo, and the California Environmental Protection Agency, Department of Toxic Substances Control. An electronic version of this submittal is being sent via email.

Please submit your comments to me at the above address or via e-mail at <u>Stephen.Farley@ch2m.com</u> by November 14, 2008.

If you have any questions regarding this document, please contact me at 707/562-1015 extension 103 or Michael Sanchez at 530/229-3310.

Sincerely,

CH2M HILL

Michael Sanchez Project Manager Stephen M. Farley, P.G. Quality Control Manager Mr. Henry Chui October 15, 2008 Page 2

Copy to (with enclosures):

Mr. Paisha Jorgensen Regional Water Quality Control Board 1515 Clay Street, Suite 1400 Oakland, CA 94612 (Non-PCB documents only; Also electronic copy of non-PCB documents) Mr. Gordon Hart Paul, Hastings, Janofsky, Walker, LLP 55 Second Street, 24th Floor San Francisco, CA 94105-3411

Ms. Carolyn d'Almeida U.S. EPA Region 9 (SFD 8-1) 75 Hawthorne Street, 9th Floor San Francisco, CA 94105 Mr. Gil Hollingsworth Mare Island Conversion Division City of Vallejo 555 Santa Clara Street Vallejo, CA 94590-5934 (Electronic copy only)

Mr. Neal Siler Lennar Mare Island, LLC 690 Walnut Avenue, Suite 100 Vallejo, CA 94592 Ms. Myrna Hayes 816 Branciforte Street Vallejo, CA 94590

Mr. Bob Palmer Caretaker Site Office, SF Bay 410 Palm Ave., Bldg. 1, Suite 161 San Francisco, CA 94130 (2 copies) Mr. Saul Bloom Arc Ecology 4634 – 3rd Street San Francisco, CA 94124 (Electronic copy only)

Ms. Sheila Roebuck Lennar Mare Island, LLC 690 Walnut Avenue, Suite 100 Vallejo, CA 94592 (Electronic copy of IAs D1 and H2 only)

CH2M HILL copies:

Paula Bolio
Clemena Balbuena
Jen Tausch
Starr Dehn (final link only)
John Romie (Paper and electronic copy of all
FOPL documents, otherwise electronic copy
of final documents only)

Mr. Henry Chui October 15, 2008 Page 3

Copy to (without enclosures):

Ms. Janet Whitlock U.S. Fish and Wildlife Service 2800 Cottage Way, Room W-2605 Sacramento, CA 95825 Mr. Justice Budu 107 Fieldstone Way Vallejo, CA 94589

Ms. Laurie Sullivan
National Oceanic and Atmospheric
Administration
75 Hawthorne Street, 9th Floor
San Francisco, CA 94105
(Electronic copy only via email)

Ms. Patricia Port U.S. Department of Interior 1111 Jackson Street, Suite 520 Oakland, CA 94607

Mr. Ron Pilkington Bay Area Air Quality Management District 939 Ellis Street San Francisco, CA 94109 Mr. Mike Coffey 6 Oricle Court American Canyon, CA 94503

Mr. Kenneth Browne 109 El Camino Real Vallejo, CA 94590 Mr. James O'Loughlin 1449 Sheridan Drive Napa, CA 94558

Mr. Adam A. Chavez 1031 Florida Street Vallejo, CA 94590-5513 Mr. Max Delaney San Francisco Bay Commission 50 California Street, Suite 2600 San Francisco, CA 94102

Mr. Gerald Karr 149 Garden Court Vallejo, CA 94591 Mr. Terry Schmidtbauer Dept. of Resource Management County of Solano 675 Texas Street, Suite 5500 Fairfield, CA 94533

Ms. Paula Tygielski 456 East L Street Benicia, CA 94510 Mr. Donald Parker Vallejo Fire Department 970 Nimitz Street Vallejo, CA 94592 Site Characterization and Cleanup Action Summary Report for Polychlorinated Biphenyl Sites Building 116 AL#01 and AL#02, Investigation Area C2, Lennar Mare Island, Vallejo, California

Prepared for Department of Toxic Substances Control

October 2008

CH2MHILL

155 Grand Avenue, Suite 1000 Oakland, CA 94612

Contents

		Page
Secti	ion	
Acro	nyms and Abbreviations	iii
1.0	Introduction	1-1
2.0	Site Identification and Background	2-2
3.0	Cleanup Action Summary	·
4.0	Polychlorinated Biphenyl Site Closure Process	4-1
5.0	Conclusions	5-1
6.0	References	6-1
App	endices	
A B	CH2M HILL Verification Sampling Analytical Data Waste Manifests for PCB Sites Building 116 AL#01 and AL#02	
	Tables	
	(located at the end of each section)	
2-1	Previous Sample Results for PCB Site Building 116 AL#01	2-5
2-2	Previous Sample Results for PCB Site Building 116 AL#02	2-8
3-1	Verification Sample Results for PCB Sites Building 116 AL#01 and AL#02	3-3
	Figures	
	(located at the end of each section)	
2-1	Location of Building 116 Former Transformer Room	2-9
2-2	PCB Sites Building 116 AL#01 and AL#02 Previous Sampling Locations and PCB Concentrations	2-10
2-3	PCB Sites Building 116 AL#01 and AL#02 PCB Concentrations prior to CH2M HILL Removal Action	2-11
3-1	PCB Sites Building 116 AL#01 and AL#02 Removal Area and Verification Sampling Locations	3-5

Acronyms and Abbreviations

 $\mu g/100 \text{ cm}^2$

micrograms per 100 square centimeters

bgs

below ground surface

CERCLA

Comprehensive Environmental Response, Compensation, and

Liability Act of 1980

Cleanup Plan

Cleanup Plan for Polychlorinated Biphenyl Sites Building 116

AL#01 and AL#02 in Investigation Area C1, Eastern Early Transfer Parcel, Lennar Mare Island, Vallejo, California

DTSC

State of California Environmental Protection Agency, Department

of Toxic Substances Control

LMI

Lennar Mare Island, LLC

mg/kg

milligrams per kilogram

Navy

United States Department of the Navy

NFA

no further action

PCB

polychlorinated biphenyl

PRG

preliminary remediation goal

SSPORTS

Supervisor of Shipbuilding, Conversion and Repair, Portsmouth,

Virginia, Environmental Detachment

TtEMI

Tetra Tech Environmental Management, Inc.

TWD

Technical Work Document

1.0 Introduction

This report summarizes the polychlorinated biphenyl (PCB) cleanup actions performed by CH2M HILL at PCB Sites Building 116 AL#01 and AL#02 in Investigation Area C2 of Lennar Mare Island, LLC's (LMI), Eastern Early Transfer Parcel. CH2M HILL prepared this summary in compliance with the Consent Agreement signed April 16, 2001, by LMI, the City of Vallejo, and the State of California Environmental Protection Agency, Department of Toxic Substances Control (DTSC) (LMI et al. 2001). The Consent Agreement specifies requirements for obtaining regulatory closure for sites of environmental concern in a manner that is consistent with the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA).

The cleanup action performed by CH2M HILL at PCB Sites Building 116 AL#01 and AL#02 consisted of demolishing the former transformer room and excavating the underlying soil. This cleanup action was conducted in accordance with the DTSC-approved "Cleanup Plan for Polychlorinated Biphenyl Sites Building 116 AL#01 and AL#02 in Investigation Area C1, Eastern Early Transfer Parcel, Lennar Mare Island, Vallejo, California" (Cleanup Plan) (CH2M HILL 2007; DTSC 2007). The objectives of the cleanup action were achieved and the remaining total PCB concentrations at these sites meet the criteria for no further action (NFA) under CERCLA.

This document is organized into the following sections:

- Section 1.0 Introduction. Provides an introduction to this report.
- Section 2.0 Site Identification and Background. Provides site background and a description of previous sampling efforts.
- Section 3.0 Cleanup Action Summary. Provides a description of CH2M HILL's cleanup actions at PCB Sites Building 116 AL#01 and AL#02.
- Section 4.0 Polychlorinated Biphenyl Site Closure Process. Provides the rationale for site closure.
- Section 5.0 Conclusions. Provides conclusions for this report.
- Section 6.0 References. Provides references for documents used to prepare this report.

2.0 Site Identification and Background

Building 116 and the former transformer room are located west of Nimitz (formerly California) Avenue and Building 52, east of Railroad Avenue, north of Rickover Street, and south of Buildings 330 and 434, in Investigation Area C2. Figure 2-1 shows the locations of Building 116 and the former transformer room. Building 116 was built in 1905 and initially served as a production shop. The transformer room attached along the northern wall of Building 116 was used to house transformers associated with Building 116. The building and former transformer room are located in an area designated as the historic core of Mare Island. According to the *Preliminary Land Use Plan* (SWA Group 2000), the proposed future use for Building 116 is industrial. Although Building 116 is not scheduled for deconstruction, it was determined that the former transformer room (PCB Sites Building 116 AL#01 and AL#02) attached to Building 116 did not have the same historic significance and, therefore, could be deconstructed (Siler 2006, pers. comm.).

Two PCB sites associated with the Building 116 former transformer room are listed in the Consent Agreement (LMI et al. 2001): AL#01 and AL#02. PCB Site Building 116 AL#01 includes the transformer pad and northwestern wall of the former transformer room. PCB Site Building 116 AL#02 is the floor drain located in the former transformer room (Figure 2-2). Documentation of United States Department of the Navy (Navy) PCB site assessment sampling, cleanup actions, and confirmation sampling for the two Building 116 PCB sites is contained in the *Final Basewide Polychlorinated Biphenyl Confirmation Sampling Summary Report* (Tetra Tech Environmental Management, Inc. [TtEMI] 1998), in the section for Parcel 04-B1.

The transformer room was a small structure, approximately 11 by 24 feet, attached to the outside, northwest wall of Building 116 (Figure 2-1). As part of the initial assessment at PCB Sites Building 116 AL#01 and AL#02, personnel from Supervisor of Shipbuilding, Conversion and Repair, Portsmouth, Virginia, Environmental Detachment (SSPORTS) collected six samples (6150-0154 through 6150-0159) on June 4, 1996, in stained areas of the concrete floor (Figure 2-2). PCBs were detected in four samples, at total concentrations of 119 (6150-0154), 4.0 (6150-0155), 788 (6150-0156), and 53,400 milligrams per kilogram (mg/kg) (6150-0157). PCB concentrations were below reporting limits in samples 6150-0158 (less than 1 mg/kg) and 6150-0159 (i.e., less than a reporting limit of 1 mg/kg in each sample) (Table 2-1); however, collection locations for these two samples were not provided in historical documentation for the sites. Because PCBs were detected at concentrations ranging from 4 to 53,400 mg/kg in these six samples, SSPORTS issued Technical Work Document (TWD) 96-1350 on October 23, 1996, to remove contamination in the former transformer room (SSPORTS 1996a).

Tables 2-1 and 2-2 summarize the results of previous sampling at PCB Sites Building 116 AL#01 and AL#02, respectively, including the sample (or boring) numbers, matrices, dates, and total PCB concentrations (or laboratory reporting limits if PCBs were not detected). Figure 2-2 shows the sampling locations and PCB concentrations prior to cleanup actions by SSPORTS) and CH2M HILL at PCB Sites Building 116 AL#01 and AL#02. Figure 2-3 shows

RDD/080730003 (NLH3728.DOC) 2-1

the sampling locations remaining after implementation of SSPORTS TWDs and PCB concentrations prior to CH2M HILL's cleanup actions at PCB Sites Building 116 AL#01 and AL#02 (SSPORTS 1996a and 1998).

2.1 PCB Site Building 116 AL#01

On February 13, 1997, before cleanup actions were performed, 28 solid floor and wall samples (7037-0064, 7037-0065, 7037-0067 through 7037-0069, 7037-0071 through 7037-0076, and 7037-0078 through 7037-0094) and 5 wipe samples (7307-0100 through 7307-0104) were collected from PCB Site Building 116 AL#01 (Figure 2-2) (SSPORTS 1996b). PCBs were detected in 27 solid samples, at concentrations ranging from 1.2 to 15,100 mg/kg (Table 2-1). PCBs were detected in four wipe samples, at concentrations ranging from 28 to 25,200 micrograms per 100 square centimeters (μ g/100 cm²) (Table 2-1). Wipe sample locations and media were not provided with the historical data for this site. Eight additional samples (7135-0082 through 7135-0089) were collected from the walls and floor in PCB Site Building 116 AL#01 on June 10, 1997 (Figure 2-2). PCB concentrations ranged from 1.7 to 25 mg/kg in those samples (Table 2-1).

In July 1997, the Navy performed cleanup in accordance with TWD 96-1350 to remove the concrete floor of PCB Site Building 116 AL#01 (SSPORTS 1996b). The floor of the site was scabbled to specified depths according to PCB concentrations in samples collected before the TWD was issued, as follows:

- Area A, which contained sample locations 6150-0154 (119 mg/kg) and 6150-0155 (4 mg/kg), was scabbled to a depth of 0.25 inch below ground surface (bgs).
- Area B, which contained sample location 6150-0156 (788 mg/kg), was scabbled to 0.5 inch bgs.
- Area C, which contained sample location 6150-0157 (maximum concentration of 53,400 mg/kg), was scabbled to 0.75 inch bgs.
- Area D (sides of utility vault) was scabbled to 0.25 inch bgs in unstained areas and to 0.75 inch where stains were visible.

According to historical Navy documentation, two additional samples (6150-0158 and 6150-0159) were collected at PCB Sites Building 116 AL#01 and AL#02 prior to implementation of TWD 96-1350, but their locations were not provided (Figure 2-2). In addition, the Navy collected 36 solid (concrete) and 5 wipe (media unknown) samples at PCB Sites Building 116 AL#01 and AL#02 from the date TWD 96-1350 was issued to the date the TWD was implemented. PCB concentrations in these samples are shown in Table 2-1 and on Figure 2-2. Areas scabbled by the Navy during implementation of TWD 96-1350 are shown on Figure 2-2. In addition to scabbling, the Navy double-washed accessible conduit and metal support surfaces as high as 12 inches above the floor, utility vault cover plates, and steel rails with kerosene and rinsed them, in accordance with TWD 96-1350 (SSPORTS 1996a).

After TWD 96-1350 had been implemented, TtEMI personnel collected two confirmation samples at PCB Site Building 116 AL#01 on July 16, 1997 (Figure 2-2). Total PCBs were reported at a concentration of 0.06J¹ mg/kg in sample PC1441, and at a concentration of 0.4J mg/kg in sample PC1442 (TtEMI 1998) (Table 2-1). Because of these results, PCB assessment and cleanup activities were considered complete (SSPORTS 1996b; TtEMI 1998).

On October 20, 2006, CH2M HILL conducted a soil boring investigation to evaluate the vertical extent of PCB contamination at PCB Site Building 116 AL#01. Three soil borings (B116AL01-GB0101, B116AL01-GB0103, and B116AL01-GB0106) were advanced at PCB Site Building 116 AL#01 to an approximate depth of 10 feet bgs and soil samples were collected from each boring at depths of 2, 4, 6, and 9 feet bgs (Figure 2-2). Boring B116AL01-GB0102 was advanced within the footprint of Building 116 AL#01 to an approximate depth of 4 feet bgs and samples were collected at depths of 2 and 4 feet bgs. The total PCB concentration in soil sample collected from boring B116AL01-GB0101 at 2 feet bgs was 0.051 mg/kg. The total PCB concentrations in the other soil samples collected from these borings were below reporting limits (which ranged from 0.0018 to 0.026 mg/kg). One composite sample was collected from concrete at boring locations B116AL01-GB0101 through B116AL01-GB0103 and B116AL01-GB0106. PCBs were detected at a total concentration of 1,000 mg/kg (Aroclor-1260) in this composite concrete sample (B116AL01-CH0107-CO).

2.2 PCB Site Building 116 AL#02

On February 13, 1997, before performing cleanup activities at PCB Site Building 116 AL#02, SSPORTS personnel collected three samples (7037-0066, 7037-0070, and 7037-0077) from PCB Site Building 116 AL#02 (Figure 2-2). PCBs were detected at total concentrations of 2.2 mg/kg in sample 7037-0066, 2.5 mg/kg in sample 7037-0070, and 18 mg/kg in sample 7037-0077 (Table 2-2).

On June 9, 1997, SSPORTS personnel collected one wipe sample (7135-0055) from the floor drain at the northern end of PCB Site Building 116 AL#02 (SSPORTS 1996b). PCBs were detected at a concentration of $69 \,\mu g/100 \, cm^2$ in that wipe sample, but the exact sample collection location was not identified in the historical documentation. Because PCB concentrations in sample 7135-0055 were above $1 \,\mu g/100 \, cm^2$, SSPORTS personnel issued TWD 96-1350, Revision A (SSPORTS 1998), which specified removing concrete within a 1-foot radius of the floor drain and excavating and removing the underlying crushed rock foundation and soil. Removal actions under TWD 96-1350, Revision A, were performed in January 1999. TWD 96-1350, Revision A, did not include cleanup goals for this removal action.

In January 1999, three samples (9-0091, 9-0092, and 9-0102) were collected from PCB Site Building 116 AL#02 prior to removal of concrete, soil, and pipes under TWD 96-1350, Revision A (Figure 2-2). Laboratory reports for these samples indicated that sample 9-0091 was collected from sediment in the drain pipe (6.6 mg/kg), sample 9-0092 was collected from soil beneath the drain pipe (1.0 mg/kg), and sample 9-0102 was collected from the interior of the drain pipe (4.9 mg/kg). Sample locations have been estimated on Figure 2-2.

RDD/080730003 (NLH3728.DOC) 2-3

^{1&}quot;J" indicates an estimated concentration.

The drain pipe and the overlying concrete were removed during the implementation of TWD 96-1350, Revision A, and disposed of off site (SSPORTS 1998).

TtEMI personnel collected two confirmation samples (PC7109 and PC7110) at PCB Site Building 116 AL#02 on February 19, 1999 (Figure 2-2). PCBs were detected at a total concentration of 0.2 mg/kg in sample PC7109, collected from soil beneath the former drain pipe. The total PCB concentration was 5 mg/kg in sample PC7110, composed of concrete collected from the surface of the remaining portion of the transformer pad, directly adjacent to the former drain location (TtEMI 1998) (Table 2-2).

On October 20, 2006, CH2M HILL conducted a soil boring investigation to evaluate the vertical extent of PCB contamination at PCB Site Building 116 AL#02. Two soil borings (B116AL01-GB0104 and B116AL01-GB0105) were advanced to approximately 10 feet bgs within the footprint of PCB Site Building 116 AL#02 and soil samples were collected at depths of 2, 4, 6, and 9 feet bgs (Figure 2-2). PCBs were detected in two samples from boring B116AL01-GB0104 at 2 feet bgs at a total concentration of 4.5 mg/kg and in one sample collected from boring B116AL01-GB0105 at 2 feet bgs at a total concentration of 0.23 mg/kg. Total PCB concentrations in other soil samples from these borings were below reporting limits (which ranged from 0.016 to 0.019 mg/kg) (Table 2-2).

TABLE 2-1
Previous Sample Results for PCB Site Building 116 AL#01
Site Characterization and Cleanup Action Summary Report for Polychlorinated Biphenyl Sites Building 116 AL#01 and AL#02, Investigation Area C2, Lennar Mare Island, Vallejo, California

Sample or Boring Number	Depth (bgs)	Sample Matrix	Sample Date	Total PCB Concentration ^a	Comments
6150-0154	0	Concrete	06/04/96	119 mg/kg	Aroclor-1260 = 119 mg/kg; stain- specific sample; removed under TWD 96-1350
6150-0155	0	Concrete	06/04/96	4 mg/kg	Aroclor-1260 = 4 mg/kg; stain- specific sample; removed under TWD 96-1350
6150-0156	0	Concrete	06/04/96	788 mg/kg	Aroclor-1260 = 788 mg/kg; stain- specific sample; removed under TWD 96-1350
6150-0157	0	Concrete	06/04/96	53,400 mg/kg	Aroclor-1260 = 53,400 mg/kg; stain- specific sample; removed under TWD 96-1350
6150-0158	0	Concrete	06/04/96	<1 mg/kg	Stain-specific sample; removed under TWD 96-1350
6150-0159	0 .	Gravel	06/04/96	<1 mg/kg	Stain-specific sample; removed under TWD 96-1350
7037-0064	0	Concrete	02/13/97	<1 mg/kg	Sample removed under TWD 96-1350
7037-0065	0	Concrete	02/13/97	4.6 mg/kg	Aroclor-1260 = 4.6 mg/kg; removed under TWD 96-1350
7037-0067	0	Concrete	02/13/97	1.2 mg/kg	Aroclor-1260 = 1.2 mg/kg; removed under TWD 96-1350
7037-0068	0	Concrete	02/13/97	2.5 mg/kg	Aroclor-1260 = 2.5 mg/kg; removed under TWD 96-1350
7037-0069	. 0	Concrete	02/13/97	11 mg/kg	Aroclor-1260 = 11 mg/kg; removed under TWD 96-1350
7037-0071	0	Concrete	02/13/97	2.1 mg/kg	Wall sample; Aroclor-1260 = 2.1 mg/kg
7037-0072	. 0	Concrete	02/13/97	1.9 mg/kg	Wall sample; Aroclor-1260 = 1.9 mg/kg
7037-0073	0	Concrete	02/13/97	82 mg/kg	Aroclor-1260 = 82 mg/kg; removed under TWD 96-1350
7037-0074	0	Concrete	02/13/97	68 mg/kg	Aroclor-1260 = 68 mg/kg; removed under TWD 96-1350
7037-0075	0 .	Concrete	02/13/97	24 mg/kg	Aroclor-1260 = 24 mg/kg; removed under TWD 96-1350
7037-0076	0	Concrete	02/13/97	6.8 mg/kg	Aroclor-1260 = 6.8 mg/kg; removed under TWD 96-1350
7037-0078	0	Concrete	02/13/97	35 mg/kg	Wall sample; Aroclor-1260 = 35 mg/kg
7037-0079	0	Concrete	02/13/97	41 mg/kg	Wall sample; Aroclor-1260 = 41 mg/kg
7037-0080	0	Concrete	02/13/97	21 mg/kg	Wall sample, Aroclor-1260 = 21 mg/kg
7037-0081	0	Concrete	02/13/97	620 mg/kg	Wall sample; Aroclor-1260 = 620 mg/kg

TABLE 2-1
Previous Sample Results for PCB Site Building 116 AL#01
Site Characterization and Cleanup Action Summary Report for Polychlorinated Biphenyl Sites Building 116 AL#01 and AL#02, Investigation Area C2, Lennar Mare Island, Vallejo, California

Sample or Boring Number	Depth (bgs)	Sample Matrix	Sample Date	Total PCB Concentration ^a	Comments
7037-0082	0	Concrete	02/13/97	620 mg/kg	Aroclor-1260 = 620 mg/kg; removed under TWD 96-1350
7037-0083	0	Concrete	02/13/97	99 mg/kg	Aroclor-1260 = 99 mg/kg; removed under TWD 96-1350
7037-0084	0.	Concrete	02/13/97	670 mg/kg	Aroclor-1260 = 670 mg/kg; removed under TWD 96-1350
7037-0085	0	Concrete	02/13/97	15,100 mg/kg	Aroclor-1260 = 15,100 mg/kg; removed under TWD 96-1350
7037-0086	0	Concrete	02/13/97	7,600 mg/kg	Aroclor-1260 = 7,600 mg/kg; removed under TWD 96-1350
7037-0087	0	Concrete	02/13/97	6,400 mg/kg	Aroclor-1260 = 6,400 mg/kg; removed under TWD 96-1350
7037-0088	0	Concrete	02/13/97	11,200 mg/kg	Aroclor-1260 = 11,200 mg/kg; removed under TWD 96-1350
7037-0089	0	Concrete	02/13/97	10,000 mg/kg	Aroclor-1260 = 10,000 mg/kg; Sample removed under TWD 96-1350
7037-0090	0	Concrete	02/13/97	11,400 mg/kg	Aroclor-1260 = 11,400 mg/kg; removed under TWD 96-1350
7037-0091	0	Concrete	02/13/97	204 mg/kg	Aroclor-1260 = 204 mg/kg; removed under TWD 96-1350
7037-0092	0	Concrete	02/13/97	1,230 mg/kg	Aroclor-1260 = 1,230 mg/kg; removed under TWD 96-1350
7037-0093	0	Concrete	02/13/97	7,000 mg/kg	Wall sample; Aroclor-1260 = 7,000 mg/kg
7037-0094	0	Concrete	02/13/97	3.8 mg/kg	Aroclor-1260 = 3.8 mg/kg; removed under TWD 96-1350
7037-0100	0	Unknown	02/13/97	25,200 μg/100 cm	Aroclor-1260 = 25,200 μg/100 cm²
7037-0101	0	Unknown	02/13/97	190 μg/100 cm²	Aroclor-1260 = 190 μg/100 cm²
7037-0102	0	Unknown	02/13/97	2,450 µg/100 cm²	Aroclor-1260 = 2,450 μg/100 cm ²
7037-0103	0	Unknown	02/13/97	28 µg/100 cm²	Aroclor-1260 = 28 μg/100 cm ²
7037-0104	0	Unknown	02/13/97	<1 µg/100 cm²	
7135-0082	0	Concrete	06/10/97	13 mg/kg	Wall sample; Aroclor-1260 = 13 mg/kg
7135-0083	0	Concrete	06/10/97	2.6 mg/kg	Wall sample; Aroclor-1260 = 2.6 mg/kg
7135-0084	0	Concrete	06/10/97	1.7 mg/kg	Wall sample; Aroclor-1260 = 1.7 mg/kg
7135-0085	0	Concrete	06/10/97	3.5 mg/kg	Wall sample; Aroclor-1260 = 3.5 mg/kg
7135-0086	0	Concrete	06/10/97	7.6 mg/kg	Trench sample; Aroclor-1260 = 7.6 mg/kg
7135-0087	0	Concrete	06/10/97	25 mg/kg	Trench sample; Aroclor-1260 = 25 mg/kg

TABLE 2-1
Previous Sample Results for PCB Site Building 116 AL#01
Site Characterization and Cleanup Action Summary Report for Polychlorinated Biphenyl Sites Building 116 AL#01 and AL#02, Investigation Area C2, Lennar Mare Island, Vallejo, California

Sample or Boring Number	Depth (bgs)	Sample Matrix	Sample Date	Total PCB Concentration ^a	Comments
7135-0088	0 .	Concrete	06/10/97	2.3 mg/kg	Wall sample, Aroclor-1260 = 2.3 mg/kg
7135-0089	0	Concrete	06/10/97	2.0 mg/kg	Wall sample; Aroclor-1260 = 2.0 mg/kg
PC1441	0	Concrete	07/16/97	0.06J mg/kg	Aroclor-1260 = 0.06J mg/kg; TWD 96-1350 confirmation sample
PC1442	0	Concrete	07/16/97	0.4J mg/kg	Aroclor-1260 = 0.4J mg/kg; TWD 96-1350 confirmation sample
B116AL01-GB0101	2	Soil	10/20/06	0.051 mg/kg	Arcolor-1260 = 0.051 mg/kg
B116AL01-GB0101	4	Soil	10/20/06	<0.017 mg/kg	Proxy value used for Arcolor-1260 0.017 mg/kg
B116AL01-GB0101	6	Soil	10/20/06	<0.024 mg/kg	Proxy value used for Arcolor-1260 0.024 mg/kg
B116AL01-GB0101	9	Soil	10/20/06	<0.0018 mg/kg	Proxy value used for Arcolor-1260 0.0018 mg/kg
B116AL01-GB0102	2	Soil	10/20/06	<0.018 mg/kg	Proxy value used for Arcolor-1260 0.018 mg/kg
B116AL01-GB0102	4	Soil	10/20/06	<0.019 mg/kg	Proxy value used for Arcolor-1260 0.019 mg/kg
B116AL01-GB0103	2	Soil	10/20/06	<0.016 mg/kg	Proxy value used for Arcolor-1260 0.016 mg/kg
B116AL01-GB0103	4	Soil	10/20/06	<0.019 mg/kg	Proxy value used for Arcolor-1260 0.019 mg/kg
B116AL01-GB0103	6	Soil	10/20/06	<0.019 mg/kg	Proxy value used for Arcolor-1260 0.019 mg/kg
B116AL01-GB0103	9	Soil	10/20/06	<0.026 mg/kg	Proxy value used for Arcolor-1260 0.026 mg/kg
B116AL01-GB0106	2	Soil	10/20/06	<0.019 mg/kg	Proxy value used for Arcolor-1260 0.019 mg/kg
B116AL01-GB0106	4	Soil	10/20/06	<0.02 mg/kg	Proxy value used for Arcolor-1260 0.02 mg/kg
B116AL01-GB0106	6	Soil	10/20/06	<0.018 mg/kg	Proxy value used for Arcolor-1260 0.018 mg/kg
B116AL01-GB0106	9	Soil	10/20/06	<0.017 mg/kg	Proxy value used for Arcolor-1260 0.017 mg/kg
B116AL01-CH0107	0	Concrete	10/20/06	1,000 mg/kg	Composite sample; Arcolor-1260 = 1,000 mg/kg

^aFor samples collected by CH2M HILL, total PCBs are calculated by summing all of the detected Aroclors or by using a proxy value of one-half the method detection limit for historically detected Aroclors and adding this to detected Aroclors.

Notes:

Sample numbers beginning with PC were collected by TtEMI. Sample numbers beginning with B were collected by CH2M HILL. Other samples were collected by SSPORTS.

Samples collected by TtEMI were reported to one significant figure.


TABLE 2-2
Previous Sample Results for PCB Site Building 116 AL#02
Site Characterization and Cleanup Action Summary Report for Polychlorinated Biphenyl Sites Building 116 AL#01 and AL#02, Investigation Area C2, Lennar Mare Island, Vallejo, California


Sample or Boring Number	Depth (bgs)	Sample Matrix	Sample Date	Total PCB Concentration ^a	Comments
7037-0066	0	Concrete	02/13/97	2.2 mg/kg	Aroclor-1260 = 2.2 mg/kg; removed under TWD 96-1350, Revision A
7037-0070	. 0	Concrete	02/13/97	2.5 mg/kg	Aroclor-1260 = 2.5 mg/kg
7037-0077	0	Concrete	02/13/97	18 mg/kg	Aroclor-1260 = 18 mg/kg; removed under TWD 96-1350, Revision A
7135-0055	0	Steel	06/09/97	69 μg/100 cm²	Aroclor-1260 = 69 µg/100 cm ² ; removed under TWD 96-1350, Revision A
9-0091	0	Sediment	01/21/99	6.6 mg/kg	Aroclor-1260 = 6.6 mg/kg; removed under TWD 96-1350, Revision A; sediment in drain pipe
9-0092	0	Soil	01/21/99	1 mg/kg	Aroclor-1260 = 1.0 mg/kg; removed under TWD 96-1350, Revision A; soil beneath drain pipe
9-0102	0	Solid	01/25/99	4.9 mg/kg	Aroclor-1260 = 4.9 mg/kg; sample removed under TWD 96-1350, Revision A; solid from drain pipe interior
PC7109	0	Soil	02/19/99	0.2 mg/kg	Aroclor-1260 = 0.2 mg/kg; TtEMI confirmation sample
PC7110	0	Concrete	02/19/99	5 mg/kg	Aroclor-1260 = 5 mg/kg; TtEMI confirmation sample
B116AL01-GB0104-	2	Soil	10/20/06	4.5 mg/kg	Arcolor-1260 = 4.5 mg/kg
B116AL01-GB0104-	4	Soil	10/20/06	<0.018 mg/kg	Proxy value used for Arcolor-1260 0.018 mg/kg
B116AL01-GB0104-	6	Soil	10/20/06	<0.018 mg/kg	Proxy value used for Arcolor-1260 0.018 mg/kg
B116AL01-GB0104-	9	Soil	10/20/06	<0.018 mg/kg	Proxy value used for Arcolor-1260 0.018 mg/kg
B116AL01-GB0105-S2	2	Soil	10/20/06	0.23 mg/kg	Arcolor-1260 = 0.23 mg/kg
B1.16AL01-GB0105-	4 .	Soil	10/20/06	<0.016 mg/kg	Proxy value used for Arcolor-1260 0.016 mg/kg
B116AL01-GB0105-	6	Soil	10/20/06	<0.019 mg/kg	Proxy value used for Arcolor-1260 0.019 mg/kg
B116AL01-GB0105-	9	Soil	10/20/06	<0.019 mg/kg	Proxy value used for Arcolor-1260 0.019 mg/kg


^aFor samples collected by CH2M HILL, total PCBs are calculated by summing all of the detected Aroclors or by using a proxy value of one-half the method detection limit for historically detected Aroclors and adding this to detected Aroclors. Notes:

Sample numbers beginning with PC were collected by TtEMI. Sample numbers beginning with B were collected by CH2M HILL. Other samples were collected by SSPORTS.

Samples collected by TtEMI were reported to one significant figure.







3.0 Cleanup Action Summary

CH2M HILL's cleanup action at PCB Sites Building 116 AL#01 and AL#02 consisted of deconstructing the walls, ceiling, and floor of the Building 116 former transformer room (11-foot by 24-foot room adjacent to Building 116) and excavating underlying soil in accordance with the DTSC-approved Cleanup Plan (CH2M HILL 2007; DTSC 2007), and performing modifications approved by DTSC (Chui 2007, pers. comm.). Analytical results for verification samples collected during CH2M HILL's cleanup actions are summarized in Table 3-1 and provided in Appendix A.

Deconstruction preparation work at PCB Sites Building 116 AL#01 and AL#02 began April 26, 2007. The former transformer room was secured with a temporary fence, and the outdoor active transformer pad located north of the former transformer room was covered with a plywood structure for protection during the building deconstruction. The windows of Building 116 were covered with plastic. Island Energy verified that the electrical and gas supplies to the structure were shut off prior to deconstruction. Remaining electrical conduit inside the building was removed, and lead-based paint was scraped from the walls.

Building deconstruction began on May 1, 2007, under Permit No. DM07-0007. The metal exhaust stack of the building was removed, followed by the metal building roof. Deconstruction of the concrete ceiling and walls began at the west wall and was completed on May 2, 2007. Debris was loaded into a dump truck and transported to the stockpile area at 14th Street and Nimitz Avenue.

The concrete floor and approximately 2.5 feet of underlying soil at PCB Sites Building 116 AL#01 and AL#02 were removed between May 7 and 9, 2007. The thickness of the concrete slab ranged from 6 to 12 inches and extended approximately 2 inches above the ground surface. The total depth of the removal area was 3 feet, including the concrete slab and approximately 2.5 feet of underlying soil. Excavation began at the east end of the concrete pad and proceeded westward across the site. Concrete rubble was removed and transported to the stockpile at 14th Street and Nimitz Avenue prior to disposal. The total excavated area was 11 feet wide by 24 feet long. Approximately 30 cubic yards of concrete and soil were removed during the cleanup action.

In accordance with the Cleanup Plan (CH2MHILL 2007), four, six-point composite soil verification sample were collected from the 6-foot by 7-foot areas (B116AL02CS0801 through B116AL02CS0804) and four, four-point composite soil verification samples from the 4-foot by 6-foot areas (B116AL02CS0805 through B116AL02CS0808) at a depth of 3 feet below the top of the former concrete surface. These eight verification samples (B116AL02-CS0801 through B116Al02-CS0808) were collected on May 9, 2007, and analyzed for PCBs. Total PCB concentrations in these eight samples ranged from 0.89 to 81 mg/kg (Table 3-1). Because total PCB concentrations in these samples exceeded the 0.74-mg/kg industrial preliminary remediation goal (PRG) for high-risk PCBs, additional soil was removed at PCB Sites Building 116 AL#01 and AL#02.

RDD/080730003 (NLH3728.DOC) 3-1

Because the excavation was close to the northwest wall of Building 116, it was possible that additional excavation below 3 feet bgs would pose a structural risk to Building 116. Michael Sanchez of CH2M HILL contacted Mr. Henry Chui of DTSC and received verbal authorization to modify the approach for PCB Sites Building 116 AL#01 and AL#02. Mr. Chui authorized collection of eight composite soil verification samples at both 6 and 10.5 feet bgs using a hand auger prior to removing additional soil (Chui 2007, pers. comm.). Analytical results for these 16 verification soil samples would be used to estimate the excavation depth needed to achieve the remediation goal (0.74 mg/kg) presented in the Cleanup Plan (CH2M HILL 2007). The additional excavation could then be performed and the excavation could be backfilled immediately following the removal to ensure that the structural integrity of Building 116 was not compromised.

On May 30 and 31, 2007, eight composite soil samples were collected at both 6 and 10.5 feet bgs from sample locations B116AL02CS0801 through B116AL02CS0808 at PCB Sites Building 116 AL#01 and AL#02 (Figure 3-1). Four-point composite soil samples were collected at 6 and 10.5 feet bgs at sample locations B116AL02CS0806 through B116AL02CS0808. Refusal was encountered at 7 feet bgs at the southwest subsample collection point of sample location B116AL02CS0805; therefore, a four-point composite soil sample was collected at 6 feet bgs and a three-point composite soil sample at 10.5 feet bgs at sample location B116AL02CS0805. Six-point composite soil samples were collected at 6 and 10.5 feet bgs at sample locations B116AL02CS0801 through B116AL02CS0803. An obstruction was encountered at 3.5 feet bgs at the southeast sample collection point for sample B116AL02CS0804; therefore, five-point composite soil samples were collected at 6 and 10.5 feet bgs at sample location B116AL020804. Total PCB concentrations for all soil samples collected at 6 and 10.5 feet bgs were below laboratory reporting limits (which ranged from 0.019 to 0.02 mg/kg at 6 feet bgs and 0.023 to 0.034 mg/kg at 10.5 feet bgs) (Table 3-1).

After analytical results for verification samples collected at 6 and 10.5 feet bgs were received, it was determined that the excavation at PCB Sites Building 116 AL#01 and AL#02 would continue to 5.5 feet bgs. On June 12, 2007, an additional 2.5 feet of soil were excavated from the site. The excavation was backfilled to grade with compacted gravel.

Debris and soil were transported on June 14, 2007, to Kettleman Landfill in Kettleman Hills, California, for disposal as a Toxic Substances Control Act waste. Appendix B contains copies of the waste manifests for the soil and debris.


TABLE 3-1
Verification Sample Results for PCB Sites Building 116 AL#01 and AL#02
Site Characterization and Cleanup Action Summary Report for Polychlorinated Biphenyl Sites Building 116 AL#01 and AL#02, Investigation Area C2, Lennar Mare Island, Vallejo, California

Sample Number	Sample Matrix	Sample Depth (feet bgs)	Sample Date	Total PCB Concentration ^a (mg/kg)	Comments
B116AL02CS0801	Soil	3	05/09/07	1.8	Removed during overexcavation; Aroclor-1260 = 1.8 mg/kg
B116AL02CS0801	Soil	6	05/30/07	<0.019	Proxy value used for Aroclor-1260 0.019
B116AL02CS0801	Soil	10.5	05/30/07	<0.026	Proxy value used for Aroclor-1260 0.026
B116AL02CS0802	Soil	3	05/09/07	13	Removed during overexcavation; Aroclor-1260 = 13 mg/kg
B116AL02CS0802	Soil	6	05/30/07	<0.019	Proxy value used for Aroclor-1260 0.019
B116AL02CS0802	Soil	10.5	05/31/07	<0.031	Proxy value used for Aroclor-1260 0.031
B116AL02CS0803	Soil	3	05/09/07	81	Removed during overexcavation; Aroclor-1260 = 81 mg/kg
B116AL02CS0803	Soil	6	05/30/07	<0.019	Proxy value used for Aroclor-1260 0.019
B116AL02CS0803	Soil	10.5	05/31/07	<0.034	Proxy value used for Aroclor-1260 0.034
B116AL02CS0804	Soil	. 3	05/09/07	6.7	Removed during overexcavation; Aroclor-1260 = 6.7 mg/kg
B116AL02CS0804	Soil	6	05/30/07	<0.02	Proxy value used for Aroclor-1260 0.02
B116AL02CS0804	Soil	10.5	05/31/07	<0.031	Proxy value used for Aroclor-1260 0.031
B116AL02CS0805	Soil	3	05/09/07	1.6	Removed during overexcavation; Aroclor-1260 = 1.6 mg/kg
B116AL02CS0805	Soil	6	05/30/07	<0.02	Proxy value used for Aroclor-1260 0.02
B116AL02CS0805	Soil	10.5	05/30/07	<0.023	Proxy value used for Aroclor-1260 0.023
B116AL02CS0806	Soil	3	05/09/07	11	Removed during overexcavation; Aroclor-1260 = 11 mg/kg
B116AL02CS0806	Soil	6	05/30/07	<0.02	Proxy value used for Aroclor-1260 0.02
B116AL02CS0806	Soil	10.5	05/31/07	<0.028	Proxy value used for Aroclor-1260 0.028
B116AL02CS0807	Soil	3	05/09/07	1	Removed during overexcavation; Aroclor-1260 = 1 mg/kg
B116AL02CS0807	Soil	6	05/30/07	<0.02	Proxy value used for Aroclor-1260 0.02

TABLE 3-1
Verification Sample Results for PCB Sites Building 116 AL#01 and AL#02
Site Characterization and Cleanup Action Summary Report for Polychlorinated Biphenyl Sites Building 116 AL#01 and AL#02, Investigation Area C2, Lennar Mare Island, Vallejo, California

Sample Number	Sample Matrix	Sample Depth (feet bgs)	Sample Date	Total PCB Concentration ^a (mg/kg)	Comments
B116AL02CS0807	Soil	10.5	05/30/07	<0.03	Proxy value used for Aroclor-1260 0.03
B116AL02CS0808	Soil	3	05/09/07	0.89	Removed during overexcavation; Aroclor-1260 = 0.89 mg/kg
B116AL02CS0808	Soil	6	05/30/07	<0.02	Proxy value used for Aroclor-1260 0.02
B116AL02CS0808	Soil	10.5	05/30/07	<0.029	Proxy value used for Aroclor-1260 0.029

^aTotal PCBs were calculated by summing all of the detected Aroclors or by using proxy value of one-half the method detection limit for historically detected Aroclors and adding this to detected Aroclors.



4.0 Polychlorinated Biphenyl Site Closure Process

Under CERCLA, no further action (NFA) is appropriate at a PCB site if no potential source and no PCB contamination are present (CH2M HILL 2003). Even if a potential source or PCB contamination is present in machinery or building materials, NFA is appropriate under CERCLA if there has been no release of PCBs to soil or groundwater and no visible pathway exists for migration of PCBs to soil or groundwater (CH2M HILL 2003). If there has been a known release to soil or groundwater, NFA is also appropriate if the detected PCB concentrations in soil and groundwater do not exceed applicable screening levels or if results of a site-specific risk evaluation demonstrate that potential risks associated with exposure to residual PCBs are within the risk-management range generally used to determine whether cleanup is necessary.

No further sampling or cleanup is necessary at PCB Sites Building 116 AL#01 and AL#02. Total PCB concentrations in verification samples collected from PCB Sites Building 116 AL#01 and AL#02 after cleanup actions were complete were below laboratory reporting limits, which ranged from 0.019 through 0.034 mg/kg, and the industrial PRG of 0.74 mg/kg.

Under CERCLA, an NFA determination would be protective of human health and the environment at PCB Sites Building 116 AL#01 and AL#02. The conditions for DTSC closure of PCB sites have been satisfied at these sites.

RDD/080730003 (NLH3728.DOC)

5.0 Conclusions

No further sampling or cleanup is necessary at PCB Sites Building 116 AL#01 and AL#02. In May and June of 2007, CH2M HILL removed concrete and soil containing concentrations of PCBs greater than the industrial PRG of 0.74 mg/kg (United States Environmental Protection Agency [USEPA] 2004). PCBs do not remain at PCB Sites Building 116 AL#01 and AL#02 at concentrations greater than the approved cleanup goal (0.74 mg/kg) presented in the Cleanup Plan (CH2M HILL HILL 2007; DTSC, 2007). This approved cleanup goal meets the 2004 industrial PRG for high-risk PCB mixtures (USEPA 2004). The remaining concentrations of PCBs conform to the newly published industrial screening levels for high-risk PCB mixtures (USEPA 2008). PCBs were not detected in the remaining verification samples at or above the maximum laboratory reporting limit of 0.034 mg/kg (Table 3-1 and Figure 3-1).

An NFA determination would be protective of human health and the environment at PCB Sites Building 116 AL#01 and AL#02. Under CERCLA, NFA is appropriate at PCB Sites Building 116 AL#01 and AL#02 because of the following conclusions:

- The source of the PCBs at these sites no longer exists.
- Total PCB concentrations in verification samples collected at 6 and 10.5 feet bgs were below laboratory reporting limits (maximum of 0.034 mg/kg) and the industrial PRG of 0.74 mg/kg.

The conditions for DTSC closure of PCB sites have been satisfied at these sites. Therefore, it is requested that DTSC issue an NFA determination for PCB Sites Building 116 AL#01 and AL#02.

RDD/080730003 (NLH3728.DOC)

6.0 References

- CH2M HILL. 2003. Final Polychlorinated Biphenyl Work Plan. March 7.
- ______. 2007. Letter. "Cleanup Plan for Polychlorinated Biphenyl Sites Building 116
 AL#01 and AL#02 in Investigation Area C1, Eastern Early Transfer Parcel, Lennar
 Mare Island, Vallejo, California." January 29.
- Chui, Henry/Department of Toxic Substances Control (DTSC). 2007. E-mail correspondence with Michael Sanchez/CH2M HILL regarding "PCB Site Building 116 AL#01 and AL#02." May 30.
- Department of Toxic Substances Control (DTSC). 2007. Letter. "Lennar Mare Island, PCB Clean Up Plan for PCB Site at Building 116 AL#01 and AL#02 in Investigation Area C1, Dated January 29, 2007." February 21.
- Lennar Mare Island, LLC (LMI), the City of Vallejo, and the State of California
 Environmental Protection Agency, Department of Toxic Substances Control (DTSC).
 2001. Consent Agreement Between Lennar Mare Island, the City of Vallejo, and the State of California, California Environmental Protection Agency, Department of Toxic Substances
 Control. April 16.
- Siler, Neal/Lennar Mare Island, LLC (LMI). 2006. E-mail correspondence with Michael Sanchez/CH2M HILL regarding "PCB Site Building 116 AL#01 and AL#02." October 9.
- Supervisor of Shipbuilding, Conversion and Repair, Portsmouth, Virginia, Environmental Detachment (SSPORTS). 1996a. PCB Decontamination Technical Work Document (TWD). PCB-Contaminated Transformer Pad. TWD No. 96-1350. Bldg. No. 116. October 23.
- _____. 1996b. Final Polychlorinated Biphenyl (PCB) Assessment for Property Leasing Conditions of Building 116. July 22.
- _____. 1998. PCB Decontamination Technical Work Document (TWD). PCB-Contaminated Transformer Pad. TWD No. 96-1350 REV. A. Bldg. No. 116. November 19.
- SWA Group. 2000. Preliminary Land Use Plan. May 23.
- Tetra Tech Environmental Management, Inc (TtEMI). 1998. Final Basewide Polychlorinated Biphenyl Confirmation Sampling Summary Report. February 13.
- United States Environmental Protection Agency. 2004. Region 9 Preliminary Remediation Goals. October 1.

RDD/080730003 (NLH3728.DOC) 6-1

Appendix A CH2M HILL Verification Sampling Analytical Data

Appendix A CH2M HILL Verification Sampling Analytical Data, Building 116 Draft Site Characterization and Cleanup Action Summary Report for Polychlorinated Biphenyl Site Building 116 AL#02, Investigation Area C2, Lennar Mare Island, Vallejo, California

Location of Sample	Sample Identifier	Analyte	CAS Number	QA/QC Type	Value (mg/Kg)	Flag [1]	Date and Time of Sample	Sample Beginning Depth (ft BGS)	Sample Ending Depth (ft BGS)	Removed?	Type of Sample	Source of Measuremen
CB Compounds												
B116AL02CS0801	B116AL02CS0801-S10.5	AROCLOR-1016	12674-11-2	ORIG	5.2E-02	U	5/30/2007 3:05:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0801	B116AL02CS0801-S10.5	AROCLOR-1221	11104-28-2	ORIG	5.2E-02	U	5/30/2007 3:05:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0801	B116AL02CS0801-S10.5	AROCLOR-1232	11141-16-5	ORIG	5.2E-02	U	5/30/2007 3:05:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0801	B116AL02CS0801-S10.5	AROCLOR-1242	53469-21-9	ORIG	5.2E-02	υ	5/30/2007 3:05:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0801	B116AL02CS0801-S10.5	AROCLOR-1248	12672-29-6	ORIG	5.2E-02	U	5/30/2007 3:05:00 PM	10.5	11.0	N	Composite Soil	[^] Laboratory
B116AL02CS0801	B116AL02CS0801-S10.5	AROCLOR-1254	11097-69-1	ORIG	5.2E-02	U	5/30/2007 3:05:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0801	B116AL02CS0801-S10.5	AROCLOR-1260	11096-82-5	ORIG	5.2E-02	U	5/30/2007 3:05:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0801	B116AL02CS0801-S10.5	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	2.6E-02	U	5/30/2007 3:05:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0801	B116AL02-CS0801-S3	AROCLOR-1016	12674-11-2	ORIG	2.0E-01	U·	5/9/2007 11:50:00 AM	3.0	3.5	Υ	Composite Soil	Laboratory
B116AL02CS0801	B116AL02-CS0801-S3	AROCLOR-1221	11104-28-2	ORIG	2.0E-01	υ	5/9/2007 11:50:00 AM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0801	B116AL02-CS0801-S3	AROCLOR-1232	11141-16-5	ORIG	2.0E-01	U	5/9/2007 11:50:00 AM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0801	B116AL02-CS0801-S3	AROCLOR-1242	53469-21-9	ORIG	2.0E-01	U	5/9/2007 11:50:00 AM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0801	B116AL02-CS0801-S3	AROCLOR-1248	12672-29-6	ORIG	2.0E-01	U	5/9/2007 11:50:00 AM	3.0	3.5	. Y	Composite Soil	Laboratory
B116AL02CS0801	B116AL02-CS0801-S3	AROCLOR-1254	11097-69-1	ORIG	2.0E-01	U	5/9/2007 11:50:00 AM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0801	B116AL02-CS0801-S3	AROCLOR-1260	11096-82-5	ORIG	1.8E+00	=	5/9/2007 11:50:00 AM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0801	B116AL02-CS0801-S3	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	1.8E+00	=	5/9/2007 11:50:00 AM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0801	B116AL02CS0801-S6	AROCLOR-1016	12674-11-2	ORIG	3.8E-02	U	5/30/2007 9:00:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0801	B116AL02CS0801-S6	AROCLOR-1221	11104-28-2	ORIG	3.8E-02	U	5/30/2007 9:00:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0801	B116AL02CS0801-S6	AROCLOR-1232	11141-16-5	ORIG	3.8E-02	U	5/30/2007 9:00:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0801	B116AL02CS0801-S6	AROCLOR-1242	53469-21-9	ORIG	3.8E-02	U	5/30/2007 9:00:00 AM	6.0	6.5	Ν.	Composite Soil	Laboratory
B116AL02CS0801	B116AL02CS0801-S6	AROCLOR-1248	12672-29-6	ORIG	3.8E-02	U	5/30/2007 9:00:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0801	B116AL02CS0801-S6	AROCLOR-1254	11097-69-1	ORIG	3.8E-02	U	5/30/2007 9:00:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0801	B116AL02CS0801-S6	AROCLOR-1260	11096-82-5	ORIG	3.8E-02	U	5/30/2007 9:00:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0801	B116AL02CS0801-S6	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	1.9E-02	U	5/30/2007 9:00:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0802	B116AL02CS0802-S10.5	AROCLOR-1016	12674-11-2	ORIG	6.1E-02	υ	5/31/2007 10:34:00 AM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0802	B116AL02CS0802-S10.5	AROCLOR-1221	11104-28-2	ORIG	6:1E-02	U	5/31/2007 10:34:00 AM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0802	B116AL02CS0802-S10.5	AROCLOR-1232	11141-16-5	ORIG	6.1E-02	Ū	5/31/2007 10:34:00 AM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0802	B116AL02CS0802-S10.5	AROCLOR-1242	53469-21-9	ORIG	6.1E-02	υ	5/31/2007 10:34:00 AM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0802	B116AL02CS0802-S10.5	AROCLOR-1248	12672-29-6	ORIG	6.1E-02	Ū	5/31/2007 10:34:00 AM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0802	B116AL02CS0802-S10.5	AROCLOR-1254	11097-69-1	ORIG	6.1E-02	U	5/31/2007 10:34:00 AM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0802	B116AL02CS0802-S10.5	AROCLOR-1260	11096-82-5	ORIG	6.1E-02	U	5/31/2007 10:34:00 AM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0802	B116AL02CS0802-S10.5	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	3.1E-02	U	5/31/2007 10:34:00 AM	10.5	11.0	N.	Composite Soil	Laboratory
B116AL02CS0802	B116AL02-CS0802-S3	AROCLOR-1016	12674-11-2	ORIG	1.9E+00	U	5/9/2007 12:00:00 PM	3.0	3.5	. Y	Composite Soil	Laboratory
B116AL02CS0802	B116AL02-CS0802-S3	AROCLOR-1221	11104-28-2	ORIG	1.9E+00	U	5/9/2007 12:00:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
3116AL02CS0802	B116AL02-CS0802-S3	AROCLOR-1232	11141-16-5	ORIG	1.9E+00	U.	5/9/2007 12:00:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0802	B116AL02-CS0802-S3	AROCLOR-1242	53469-21-9	ORIG	1.9E+00	U	5/9/2007 12:00:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0802	B116AL02-CS0802-S3	AROCLOR-1248	12672-29-6	ORIG	1.9E+00	U	5/9/2007 12:00:00 PM	3.0	3.5	· Y	Composite Soil	Laboratory
B116AL02CS0802	B116AL02-CS0802-S3	AROCLOR-1254	11097-69-1	ORIG	1.9E+00	U	5/9/2007 12:00:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0802	B116AL02-CS0802-S3	AROCLOR-1260	11096-82-5	ORIG	1.3E+01	=	5/9/2007 12:00:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0802	B116AL02-CS0802-S3	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	1.3E+01	=	5/9/2007 12:00:00 PM	3.0	3.5	' . V	Composite Soil	Laboratory

Detected Result

Non-Detected Result

If Sample Depth = 999, actual Sample Depth is unknown.

Appendix A CH2M HILL Verification Sampling Analytical Data, Building 116 Draft Site Characterization and Cleanup Action Summary Report for Polychlorinated Biphenyl Site Building 116 AL#02, Investigation Area C2, Lennar Mare Island, Vallejo, California

Location of Sample	Sample Identifier	Analyte	CAS Number	QA/QC Type	Value (mg/Kg)	Flag [1]	Date and Time of Sample	Sample Beginning Depth (ft BGS)	Sample Ending Depth (ft BGS)	Removed?	Type of Sample	Source of Measuremen
CB Compounds					_						-	
B116AL02CS0802	B116AL02CS0802-S6	AROCLOR-1016	12674-11-2	ORIG	3.9E-02	U	5/30/2007 9:50:00 AM	6.0	6,5	N	Composite Soil	Laboratory
B116AL02CS0802	B116AL02CS0802-S6	AROCLOR-1221	11104-28-2	ORIG	3.9E-02	U	5/30/2007 9:50:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0802	B116AL02CS0802-S6	AROCLOR-1232	11141-16-5	ORIG	3.9E-02	U	5/30/2007 9:50:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0802	B116AL02CS0802-S6	AROCLOR-1242	53469-21-9	ORIG	3.9E-02	U	5/30/2007 9:50:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0802	B116AL02CS0802-S6	AROCLOR-1248	12672-29-6	ORIG	3.9E-02	U	5/30/2007 9:50:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0802	B116AL02CS0802-S6	AROCLOR-1254	11097-69-1	ORIG	3.9E-02	U	5/30/2007 9:50:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0802	B116AL02CS0802-S6	AROCLOR-1260	11096-82-5	ORIG	3.9E-02	U	5/30/2007 9:50:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0802	B116AL02CS0802-S6	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	1.9E-02	U	5/30/2007 9:50:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0803	B116AL02CS0803-S10.5	AROCLOR-1016	12674-11-2	ORIG	6.9E-02	U	5/31/2007 10:54:00 AM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0803	B116AL02CS0803-S10.5	AROCLOR-1221	11104-28-2	ORIG	6.9E-02	U	5/31/2007 10:54:00 AM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0803	B116AL02CS0803-S10.5	AROCLOR-1232	11141-16-5	ORIG	6.9E-02	U	5/31/2007 10:54:00 AM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0803	B116AL02CS0803-S10.5	AROCLOR-1242	53469-21-9	ORIG-	6.9E-02	U	5/31/2007 10:54:00 AM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0803	B116AL02CS0803-S10.5	AROCLOR-1248	12672-29-6	ORIG	6.9E-02	U	5/31/2007 10:54:00 AM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0803	B116AL02CS0803-S10.5	AROCLOR-1254	11097-69-1	ORIG	6.9E-02	U	5/31/2007 10:54:00 AM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0803	B116AL02CS0803-S10.5	AROCLOR-1260	11096-82-5	ORIG	6.9E-02	U	5/31/2007 10:54:00 AM	10.5	11,0	. N	Composite Soil	Laboratory
B116AL02CS0803	B116AL02CS0803-S10.5	Total PCBs_B116_09272007	TOTAL PCBS B116 09272007	ORIG	3.4E-02	U	5/31/2007 10:54:00 AM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0803	B116AL02-CS0803-S3	AROCLOR-1016	12674-11-2	ORIG	6.9E+00	U	5/9/2007 12:03:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory
B116AL02CS0803	B116AL02-CS0803-S3	AROCLOR-1221	11104-28-2	ORIG	6.9E+00	U	5/9/2007 12:03:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0803	B116AL02-CS0803-S3	AROCLOR-1232	11141-16-5	ORIG	6.9E+00	υ	5/9/2007 12:03:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0803	B116AL02-CS0803-S3	AROCLOR-1242	53469-21-9	ORIG	6.9E+00	υ	5/9/2007 12:03:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0803	B116AL02-CS0803-S3	AROCLOR-1248	12672-29-6	ORIG	6.9E+00	Ū	5/9/2007 12:03:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0803	B116AL02-CS0803-S3	AROCLOR-1254	11097-69-1	ORIG	6.9E+00	Ū	5/9/2007 12:03:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0803	B116AL02-CS0803-S3	AROCLOR-1260	11096-82-5	ORIG	8.1E+01	=	5/9/2007 12:03:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0803	B116AL02-CS0803-S3	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	8.1E+01	=	5/9/2007 12:03:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0803	B116AL02CS0803-S6	AROCLOR-1016	12674-11-2	ORIG	3.9E-02	U	5/30/2007 10:30:00 AM	6.0	6.5	N.	Composite Soil	Laboratory
B116AL02CS0803	B116AL02CS0803-S6	AROCLOR-1221	11104-28-2	ORIG	3.9E-02	U	5/30/2007 10:30:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0803	B116AL02CS0803-S6	AROCLOR-1232	11141-16-5	ORIG	3.9E-02	U	5/30/2007 10:30:00 AM	6.0	6.5	. N	Composite Soil	Laboratory
B116AL02CS0803	B116AL02CS0803-S6	AROCLOR-1242	53469-21-9	ORIG	3.9E-02	Ü	5/30/2007 10:30:00 AM	6.0	6.5	N N	Composite Soil	Laboratory
B116AL02CS0803	B116AL02CS0803-S6	AROCLOR-1248	12672-29-6	ORIG	3.9E-02	U	5/30/2007 10:30:00 AM	6.0	6.5	N N	Composite Soil	Laboratory
B116AL02CS0803	B116AL02CS0803-S6	AROCLOR-1254	11097-69-1	ORIG	3.9E-02	U	5/30/2007 10:30:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0803	B116AL02CS0803-S6	AROCLOR-1260	11096-82-5	ORIG	3.9E-02	U	5/30/2007 10:30:00 AM	6.0	6.5	N N	Composite Soil	Laboratory
B116AL02CS0803	B116AL02CS0803-S6	Total PCBs B116 09272007	TOTAL PCBS_B116_09272007	ORIG	1.9E-02	U	5/30/2007 10:30:00 AM	6.0	6.5	. N	Composite Soil	Laboratory
B116AL02CS0804	B116AL02CS0804-S10.5	AROCLOR-1016	12674-11-2	ORIG	6.2E-02	U	5/31/2007 9:45:00 AM	10.5	11.0	N.	Composite Soil	Laboratory
B116AL02CS0804	B116AL02CS0804-S10.5	AROCLOR-1221	11104-28-2	ORIG	6.2E-02	U	5/31/2007 9:45:00 AM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0804	B116AL02CS0804-S10.5	AROCLOR-1232	11141-16-5	ORIG	6.2E-02	U	5/31/2007 9:45:00 AM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0804	B116AL02CS0804-S10.5	AROCLOR-1242	53469-21-9	ORIG	6.2E-02	U	5/31/2007 9:45:00 AM	10.5	11.0	N N	Composite Soil	Laboratory
B116AL02CS0804	B116AL02CS0804-S10.5	AROCLOR-1248	12672-29-6	ORIG	6.2E-02	U	5/31/2007 9:45:00 AM	10.5	11.0	! N	Composite Soil	Laboratory
B116AL02CS0804	B116AL02CS0804-S10.5	AROCLOR-1254	11097-69-1	ORIG	6.2E-02	U	5/31/2007 9:45:00 AM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0804	B116AL02CS0804-S10.5	AROCLOR-1260	11096-82-5	ORIG	6.2E-02	U	5/31/2007 9:45:00 AM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0804	B116AL02CS0804-S10.5	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	3.1E-02	Ū	5/31/2007 9:45:00 AM	10.5	11.0		Composite Soil	Laboratory

If Sample Depth = 999, actual Sample Depth is unknown.

[1] FLAGS

Detected Result

Non-Detected Result

Appendix A CH2M HILL Verification Sampling Analytical Data, Building 116 Draft Site Characterization and Cleanup Action Summary Report for Polychlorinated Biphenyl Site Building 116 AL#02, Investigation Area C2, Lennar Mare Island, Vallejo, California

Location of Sample	Sample Identifier	Analyte	CAS Number	QA/QC Type	Value (mg/Kg)	Flag [1]	Date and Time of Sample	Sample Beginning Depth (ft BGS)	Sample Ending Depth (ft BGS)	Removed?	Type of Sample	Source of Measuremen
CB Compounds												
B116AL02CS0804	B116AL02-CS0804-S3	AROCLOR-1016	12674-11-2	ORIG	7.7E-01	U	5/9/2007 12:07:00 PM	, 3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0804	B116AL02-CS0804-S3	AROCLOR-1221	11104-28-2	ORIG	7.7E-01	U	5/9/2007 12:07:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory
B116AL02CS0804	B116AL02-CS0804-S3	AROCLOR-1232	11141-16-5	ORIG	7.7E-01	U	5/9/2007 12:07:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory
B116AL02CS0804	B116AL02-CS0804-S3	AROCLOR-1242	53469-21-9	ORIG	7.7E-01	U	5/9/2007 12:07:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory
B116AL02CS0804	B116AL02-CS0804-S3	AROCLOR-1248	12672-29-6	ORIG	7.7E-01	U	5/9/2007 12:07:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0804	B116AL02-CS0804-S3	AROCLOR-1254	11097-69-1	ORIG	7.7E-01	U	5/9/2007 12:07:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0804	B116AL02-CS0804-S3	AROCLOR-1260	11096-82-5	ORIG	6.7E+00	=	5/9/2007 12:07:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory
B116AL02CS0804	B116AL02-CS0804-S3	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	6.7E+00	=	5/9/2007 12:07:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0804	B116AL02CS0804-S6	AROCLOR-1016	12674-11-2	ORIG	4.0E-02	υ	5/30/2007 11:15:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0804	B116AL02CS0804-S6	AROCLOR-1221	11104-28-2	ORIG	4.0E-02	U	5/30/2007 11:15:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0804	B116AL02CS0804-S6	AROCLOR-1232	11141-16-5	ORIG	4.0E-02	U	5/30/2007 11:15:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0804	B116AL02CS0804-S6	AROCLOR-1242	53469-21-9	ORIG	4.0E-02	U	5/30/2007 11:15:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0804	B116AL02CS0804-S6	AROCLOR-1248	12672-29-6	ORIG	4.0E-02	U	5/30/2007 11:15:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0804	B116AL02CS0804-S6	AROCLOR-1254	11097-69-1	ORIG	4.0E-02	U	5/30/2007 11:15:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0804	B116AL02CS0804-S6	AROCLOR-1260	11096-82-5	ORIG	4.0E-02	Ū	5/30/2007 11:15:00 AM	6.0	6.5	N	Composite Soil	. Laboratory
3116AL02CS0804	B116AL02CS0804-S6	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	2.0E-02	٠ υ	5/30/2007 11:15:00 AM	6.0	6.5	N	Composite Soil	Laboratory
116AL02CS0805	B116AL02CS0805-S10.5	AROCLOR-1016	12674-11-2	ORIG	4.7E-02	U	5/30/2007 2:10:00 PM	10.5	11.0	N	Composite Soil	Laboratory
3116AL02CS0805	B116AL02CS0805-S10.5	AROCLOR-1221	11104-28-2	ORIG	4.7E-02	. บ	5/30/2007 2:10:00 PM	10.5	11.0	N	Composite Soil	Laboratory
3116AL02CS0805	B116AL02CS0805-S10.5	AROCLOR-1232	11141-16-5	ORIG	4.7E-02	U	5/30/2007 2:10:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0805	B116AL02CS0805-S10.5	AROCLOR-1242	53469-21-9	ORIG	4.7E-02	U	5/30/2007 2:10:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0805	B116AL02CS0805-S10.5	AROCLOR-1248	12672-29-6	ORIG	4.7E-02	U	5/30/2007 2:10:00 PM	10.5	11.0	N	Composite Soil	Laboratory
3116AL02CS0805	B116AL02CS0805-S10.5	AROCLOR-1254	11097-69-1	ORIG	4.7E-02	U	5/30/2007 2:10:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0805	B116AL02CS0805-S10.5	AROCLOR-1260	11096-82-5	ORIG	4.7E-02	U	5/30/2007 2:10:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0805	B116AL02CS0805-S10.5	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	2.3E-02	U	5/30/2007 2:10:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0805	B116AL02-CS0805-S3	AROCLOR-1016	12674-11-2	ORIG	2.0E-01	U	5/9/2007 12:10:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory
3116AL02CS0805	B116AL02-CS0805-S3	AROCLOR-1221	11104-28-2	ORIG	2.0E-01	U	5/9/2007 12:10:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory
B116AL02CS0805	B116AL02-CS0805-S3	AROCLOR-1232	11141-16-5	ORIG	2.0E-01	U	5/9/2007 12:10:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory
B116AL02CS0805	B116AL02-CS0805-S3	AROCLOR-1242	53469-21-9	ORIG	2.0E-01	U	5/9/2007 12:10:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory
B116AL02CS0805	B116AL02-CS0805-S3	AROCLOR-1248	12672-29-6	ORIG	2.0E-01	U	5/9/2007 12:10:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory
B116AL02CS0805	B116AL02-CS0805-S3	AROCLOR-1254	11097-69-1	ORIG	2.0E-01	บ	5/9/2007 12:10:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory
B116AL02CS0805	B116AL02-CS0805-S3	AROCLOR-1260	11096-82-5	ORIG	1.6E+00	=	5/9/2007 12:10:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0805	B116AL02-CS0805-S3	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG :	1.6E+00	=	5/9/2007 12:10:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory
B116AL02CS0805	B116AL02CS0805-S6	AROCLOR-1016 .	12674-11-2	ORIG	4.1E-02	U	5/30/2007 8:45:00 AM	6.0	6.5	N	Composite Soil	Laboratory
3116AL02CS0805	B116AL02CS0805-S6	AROCLOR-1221	11104-28-2	ORIG	4.1E-02	U	5/30/2007 8:45:00 AM	6.0	6.5		Composite Soil	Laboratory
116AL02CS0805	B116AL02CS0805-S6	AROCLOR-1232	11141-16-5	ORIG	4.1E-02	U	5/30/2007 8:45:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0805	B116AL02CS0805-S6	AROCLOR-1242	53469-21-9	ORIG	4.1E-02	Ü	5/30/2007 8:45:00 AM	6.0	. 6.5	N	Composite Soil	Laboratory
B116AL02CS0805	B116AL02CS0805-S6	AROCLOR-1248	12672-29-6	ORIG	4.1E-02	Ü	5/30/2007 8:45:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0805	B116AL02CS0805-S6	AROCLOR-1254	11097-69-1	ORIG	4.1E-02	U	5/30/2007 8:45:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0805	B116AL02CS0805-S6	AROCLOR-1260	11096-82-5	ORIG	4.1E-02	U	5/30/2007 8:45:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0805	B116AL02CS0805-S6	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	2.0E-02	U	5/30/2007 8:45:00 AM	6.0	6.5	N	Composite Soil	Laboratory

If Sample Depth = 999, actual Sample Depth is unknown.

[1] FLAGS

Non-Detected Result

Appendix A CH2M HILL Verification Sampling Analytical Data, Building 116 Draft Site Characterization and Cleanup Action Summary Report for Polychlorinated Biphenyl Site Building 116 AL#02, Investigation Area C2, Lennar Mare Island, Vallejo, California

B Compounds 3116AL02CS0806 3116AL02CS0806 3116AL02CS0806 3116AL02CS0806 3116AL02CS0806 3116AL02CS0806 3116AL02CS0806 3116AL02CS0806	B116AL02CS0806-S10.5 B116AL02CS0806-S10.5 B116AL02CS0806-S10.5 B116AL02CS0806-S10.5 B116AL02CS0806-S10.5 B116AL02CS0806-S10.5 B116AL02CS0806-S10.5 B116AL02CS0806-S10.5	AROCLOR-1016 AROCLOR-1221 AROCLOR-1232 AROCLOR-1242 AROCLOR-1248 AROCLOR-1254	12674-11-2 11104-28-2 11141-16-5 53469-21-9 12672-29-6	ORIG ORIG ORIG ORIG	5.6E-02 5.6E-02	υ	5/31/2007 9:20:00 AM	10.5	11.0			
8116AL02CS0806 8116AL02CS0806 8116AL02CS0806 8116AL02CS0806 8116AL02CS0806 8116AL02CS0806	B116AL02CS0806-S10.5 B116AL02CS0806-S10.5 B116AL02CS0806-S10.5 B116AL02CS0806-S10.5 B116AL02CS0806-S10.5	AROCLOR-1221 AROCLOR-1232 AROCLOR-1242 AROCLOR-1248	11104-28-2 11141-16-5 53469-21-9	ORIG ORIG	5.6E-02		5/31/2007 9:20:00 AM	10.5	11.0			
8116AL02CS0806 8116AL02CS0806 8116AL02CS0806 8116AL02CS0806 8116AL02CS0806	B116AL02CS0806-S10.5 B116AL02CS0806-S10.5 B116AL02CS0806-S10.5 B116AL02CS0806-S10.5 B116AL02CS0806-S10.5	AROCLOR-1232 AROCLOR-1242 AROCLOR-1248	11141-16-5 53469-21-9	ORIG				. 5.5	11.0	N	Composite Soil	Laboratory
3116AL02CS0806 3116AL02CS0806 3116AL02CS0806 3116AL02CS0806	B116AL02CS0806-S10.5 B116AL02CS0806-S10.5 B116AL02CS0806-S10.5 B116AL02CS0806-S10.5	AROCLOR-1242 AROCLOR-1248	53469-21-9			U	5/31/2007 9:20:00 AM	10.5	11.0	N	Composite Soil	Laboratory
3116AL02CS0806 3116AL02CS0806 3116AL02CS0806	B116AL02CS0806-S10.5 B116AL02CS0806-S10.5 B116AL02CS0806-S10.5	AROCLOR-1248		ORIG	5.6E-02	U	5/31/2007 9:20:00 AM	10.5	11.0	N	Composite Soil	Laboratory
3116AL02CS0806 3116AL02CS0806	B116AL02CS0806-S10.5 B116AL02CS0806-S10.5		12672-29-6	0.40	5.6E-02	U	5/31/2007 9:20:00 AM	10.5	11.0	N	Composite Soil	Laboratory
3116AL02CS0806	B116AL02CS0806-S10.5	AROCLOR-1254		ORIG	5.6E-02	U	5/31/2007 9:20:00 AM	10.5	11.0	N	Composite Soil	Laboratory
			11097-69-1	ORIG	5.6E-02	U	5/31/2007 9:20:00 AM	10.5	11.0	N	Composite Soil	Laboratory
1116AL02CS0806	B116AL02CS0806-S10.5	AROCLOR-1260	11096-82-5	ORIG	5.6E-02	U	5/31/2007 9:20:00 AM	10.5	11.0	N	Composite Soil	Laboratory
		Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	2.8E-02	U	5/31/2007 9:20:00 AM	10.5	11.0	N	Composite Soil	Laboratory
3116AL02CS0806	B116AL02-CS0806-S3	AROCLOR-1016	· 12674-11-2	ORIG	7.7E-01	U	5/9/2007 12:13:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
3116AL02CS0806	B116AL02-CS0806-S3	AROCLOR-1221	11104-28-2	ORIG	7.7E-01	U	5/9/2007 12:13:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory
3116AL02CS0806	B116AL02-CS0806-S3	AROCLOR-1232	11141-16-5	ORIG	7.7E-01	U	5/9/2007 12:13:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
3116AL02CS0806	B116AL02-CS0806-S3	AROCLOR-1242	53469-21-9	ORIG	7.7E-01	υ	5/9/2007 12:13:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
3116AL02CS0806	B116AL02-CS0806-S3	AROCLOR-1248	12672-29-6	ORIG	7.7E-01	U	5/9/2007 12:13:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory
3116AL02CS0806	B116AL02-CS0806-S3	AROCLOR-1254	11097-69-1	ORIG	7.7E-01	U	5/9/2007 12:13:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory
3116AL02CS0806	B116AL02-CS0806-S3	AROCLOR-1260	11096-82-5	ORIG	1.1E+01	=	5/9/2007 12:13:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory
3116AL02CS0806	B116AL02-CS0806-S3	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	1.1E+01	=	5/9/2007 12:13:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
3116AL02CS0806	B116AL02CS0806-S6	AROCLOR-1016	12674-11-2	ORIG	4.0E-02	U	5/30/2007 9:20:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0806	B116AL02CS0806-S6	AROCLOR-1221	11104-28-2	ORIG	4.0E-02	U	5/30/2007 9:20:00 AM	6.0	6.5	N	Composite Soil	Laboratory
3116AL02CS0806	B116AL02CS0806-S6	AROCLOR-1232	11141-16-5	ORIG	4.0E-02	U	5/30/2007 9:20:00 AM	6.0	6.5	N	Composite Soil	Laboratory
3116AL02CS0806	B116AL02CS0806-S6	AROCLOR-1242	53469-21-9	ORIG	4.0E-02	υ	5/30/2007 9:20:00 AM	6.0	6.5	N	Composite Soil	Laboratory
3116AL02CS0806	B116AL02CS0806-S6	AROCLOR-1248	12672-29-6	ORIG	4.0E-02	U	5/30/2007 9:20:00 AM	6.0	6.5	N	Composite Soil	Laboratory
3116AL02CS0806	B116AL02CS0806-S6	AROCLOR-1254	11097-69-1	ORIG	4.0E-02	υ	5/30/2007 9:20:00 AM	6.0	6.5	N	Composite Soil	Laboratory
3116AL02CS0806	B116AL02CS0806-S6	AROCLOR-1260	11096-82-5	ORIG	4.0E-02	U	5/30/2007 9:20:00 AM	6.0	6.5	N	Composite Soil	Laboratory
3116AL02CS0806	B116AL02CS0806-S6	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	2.0E-02	υ	5/30/2007 9:20:00 AM	6.0	6.5	N	Composite Soil	Laboratory
3116AL02CS0807	B116AL02CS0807-S10.5	AROCLOR-1016	 12674-11-2	ORIG	6.1E-02	U	5/30/2007 3:00:00 PM	10.5	11.0	N	Composite Soil	Laboratory
3116AL02CS0807	B116AL02CS0807-S10.5	AROCLOR-1221	11104-28-2	ORIG	6.1E-02	U	5/30/2007 3:00:00 PM	10.5	11.0	N	Composite Soil	Laboratory
3116AL02CS0807	B116AL02CS0807-S10.5	AROCLOR-1232	11141-16-5	ORIG	6.1E-02	υ	5/30/2007 3:00:00 PM	10.5	11.0	N	Composite Soil	Laboratory
3116AL02CS0807	B116AL02CS0807-S10.5	AROCLOR-1242	53469-21-9	ORIG · ·	6.1E-02	U	5/30/2007 3:00:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0807	B116AL02CS0807-S10.5	AROCLOR-1248	12672-29-6	ORIG	6.1E-02	U	5/30/2007 3:00:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0807	B116AL02CS0807-S10.5	AROCLOR-1254	11097-69-1	ORIG	6.1E-02	Ú	5/30/2007 3:00:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0807	B116AL02CS0807-S10.5	AROCLOR-1260	11096-82-5	ORIG	6.1E-02	Ü	5/30/2007 3:00:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0807	B116AL02CS0807-S10.5	Total PCBs B116 09272007	TOTAL PCBS B116 09272007	ORIG	3.0E-02	U	5/30/2007 3:00:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0807	B116AL02-CS0807-S3	AROCLOR-1016	12674-11-2	ORIG	1.8E-01	U	5/9/2007 12:15:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
3116AL02CS0807	B116AL02-CS0807-S3	AROCLOR-1221	11104-28-2	ORIG	1.8E-01	υ	5/9/2007 12:15:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
3116AL02CS0807	B116AL02-CS0807-S3	AROCLOR-1232	11141-16-5	ORIG	1.8E-01	U	5/9/2007 12:15:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
3116AL02CS0807	B116AL02-CS0807-S3	AROCLOR-1242	53469-21-9	ORIG	1.8E-01	U	5/9/2007 12:15:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0807	B116AL02-CS0807-S3	AROCLOR-1248	12672-29-6	ORIG	1.8E-01	U	5/9/2007 12:15:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0807	B116AL02-CS0807-S3	AROCLOR-1254	11097-69-1	ORIG	1.8E-01	Ü	5/9/2007 12:15:00 PM	3.0	3.5	, Y	Composite Soil	Laboratory
B116AL02CS0807	B116AL02-CS0807-S3	AROCLOR-1260	11096-82-5	ORIG	1.0E+00	. =	5/9/2007 12:15:00 PM	3.0	3.5	· •	Composite Soil	Laboratory
B116AL02CS0807	B116AL02-CS0807-S3	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	1.0E+00	=	5/9/2007 12:15:00 PM	3.0	3.5	Y	Composite Soil	Laboratory

[1] FLAGS

Detected Result Non-Detected Result

If Sample Depth = 999, actual Sample Depth is unknown.

Appendix A

CH2M HILL Verification Sampling Analytical Data, Building 116

Draft Site Characterization and Cleanup Action Summary Report for Polychlorinated Biphenyl Site Building 116 AL#02, Investigation Area C2, Lennar Mare Island, Vallejo, California

Location of Sample	Sample Identifier	Analyte	CAS Number	QA/QC Type	Value (mg/Kg)	Flag [1]	Date and Time of Sample	Sample Beginning Depth (ft BGS)	Sample Ending Depth (ft BGS)	Removed?	Type of Sample	Source of Measuremen
PCB Compounds										-		
B116AL02CS0807	B116AL02CS0807-S6	AROCLOR-1016	12674-11-2	ORIG	4.0E-02	U	5/30/2007 10:00:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0807	B116AL02CS0807-S6	AROCLOR-1221	11104-28-2	ORIG	4.0E-02	U	5/30/2007 10:00:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0807	B116AL02CS0807-S6	AROCLOR-1232	11141-16-5	ORIG	4.0E-02	U	5/30/2007 10:00:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0807	B116AL02CS0807-S6	AROCLOR-1242	53469-21-9	ORIG	4.0E-02	U	5/30/2007 10:00:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0807	B116AL02CS0807-S6	AROCLOR-1248	12672-29-6	ORIG	4.0E-02	U ·	5/30/2007 10:00:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0807	B116AL02CS0807-S6	AROCLOR-1254	11097-69-1	ORIG	4.0E-02	U	5/30/2007 10:00:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0807	B116AL02CS0807-S6	AROCLOR-1260	11096-82-5	ORIG	4.0E-02	υ	5/30/2007 10:00:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0807	B116AL02CS0807-S6	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	2.0E-02	U	5/30/2007 10:00:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0808	B116AL02CS0808-S10.5	AROCLOR-1016	12674-11-2	ORIG	5.8E-02	U	5/30/2007 2:00:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0808	B116AL02CS0808-S10.5	AROCLOR-1221	11104-28-2	ORIG	5.8E-02	U	5/30/2007 2:00:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0808	B116AL02CS0808-S10.5	AROCLOR-1232	11141-16-5	ORIG	5.8E-02	U	5/30/2007 2:00:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0808	B116AL02CS0808-S10.5	AROCLOR-1242	53469-21-9	ORIG	5.8E-02	U	5/30/2007 2:00:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0808	B116AL02CS0808-S10.5	AROCLOR-1248	12672-29-6	ORIG	5.8E-02	U	5/30/2007 2:00:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0808	B116AL02CS0808-S10.5	AROCLOR-1254	11097-69-1	ORIG	5.8E-02	U	5/30/2007 2:00:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0808	B116AL02CS0808-S10.5	AROCLOR-1260	11096-82-5	ORIG	5.8E-02	U	5/30/2007 2:00:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0808	B116AL02CS0808-S10.5	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	2.9E-02	U	5/30/2007 2:00:00 PM	10.5	11.0	N	Composite Soil	Laboratory
B116AL02CS0808	B116AL02-CS0808-S3	AROCLOR-1016	12674-11-2	ORIG	1.8E-01	U	5/9/2007 12:20:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory.
B116AL02CS0808	B116AL02-CS0808-S3	AROCLOR-1221	11104-28-2	ORIG	1.8E-01	U	5/9/2007 12:20:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0808	B116AL02-CS0808-S3	AROCLOR-1232	11141-16-5	ORIG	1.8E-01	U	5/9/2007 12:20:00 PM	3.0	3.5	Υ .	Composite Soil	Laboratory
B116AL02CS0808	B116AL02-CS0808-S3	AROCLOR-1242	53469-21-9	ORIG	1.8E-01	U	5/9/2007 12:20:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory
B116AL02CS0808	B116AL02-CS0808-S3	AROCLOR-1248	12672-29-6	ORIG	1.8E-01	U	5/9/2007 12:20:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory
B116AL02CS0808	B116AL02-CS0808-S3	AROCLOR-1254	11097-69-1	ORIG	1.8E-01	U	5/9/2007 12:20:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0808	B116AL02-CS0808-S3	AROCLOR-1260	11096-82-5	ORIG	8.9E-01	=	5/9/2007 12:20:00 PM	3.0	3.5	Y	Composite Soil	Laboratory
B116AL02CS0808	B116AL02-CS0808-S3	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	8.9E-01	=	5/9/2007 12:20:00 PM	3.0	3.5	Υ	Composite Soil	Laboratory
B116AL02CS0808	B116AL02CS0808-S6	AROCLOR-1016	12674-11-2	ORIG	4.0E-02	U	5/30/2007 10:40:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02C\$0808	B116AL02CS0808-S6	AROCLOR-1221	11104-28-2	ORIG	4.0E-02	U	5/30/2007 10:40:00 AM	6.0	6.5	N	Composite Soil	· Laboratory
B116AL02CS0808	B116AL02CS0808-S6	AROCLOR-1232	11141-16-5	ORIG	4.0E-02	U	5/30/2007 10:40:00 AM	. 6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0808	B116AL02CS0808-S6	AROCLOR-1242	53469-21-9	ORIG	4.0E-02	U	5/30/2007 10:40:00 AM	6.0 ⁻	6.5	N	Composite Soil	Laboratory
B116AL02CS0808	B116AL02CS0808-S6	AROCLOR-1248	12672-29-6	ORIG	4.0E-02	U	5/30/2007 10:40:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0808	B116AL02CS0808-S6	AROCLOR-1254	11097-69-1	ORIG	4.0E-02	U	5/30/2007 10:40:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0808	B116AL02CS0808-S6	AROCLOR-1260	11096-82-5	ORIG	4.0E-02	U	5/30/2007 10:40:00 AM	6.0	6.5	N	Composite Soil	Laboratory
B116AL02CS0808	B116AL02CS0808-S6	Total PCBs_B116_09272007	TOTAL PCBS_B116_09272007	ORIG	2.0E-02	U	5/30/2007 10:40:00 AM	6.0	6.5	N	Composite Soil	Laboratory

NOTES

For samples collected by CH2M HILL, Total PCB are calculated by summing detected Aroclors or by summing detected Aroclors to a proxy value (one-half the reporting limit) for historically detected Aroclors.

If Sample Depth = 999, actual Sample Depth is unknown.

[1] FLAGS

Detected Result

J Non-Detected Result

Appendix B Waste Manifests for PCB Sites Building 116 AL#01 and AL#02

M	UNIFO	or type, (Form designed for use on eite (12-pitch) typewriter.) ORM HAZARDOUS 1. Generalor ID Number STE MANIFEST	<u></u>	nergency Response Pl	<u> </u>		racking Nu 239		JJK
֧֓֞֞֜֜֞֟֝֟֝֟֝֟֝֟֝֟֝֟֝֟֝֟֝ ֓֓֞֓֞֞֞֞֓֞֓֞֞֞֞֓֓֓֞֞֓֓֓֞	•	erator's Name and Mailing Address Education Address Island (1) Education Address Island (1) Valley (1) (1) (1) (1)	Leo Vije	ator's Site Address (if eruso Advice Islam (Pro IRA) es Internal CA	da Fi	wagned address	5)		
		ator's Prione: 1/12/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/					981	5136	7 L
		and the second s				u.s. epa ID Ni	umber		5375
	8 Des	Ignated Facility Name and Site Address Treatment Waste Kinning training		· · · · · · · · · · · · · · · · · · ·		U.S. EPA ID N			
	Facility	15751 Chl Skyltin: Read Kulthestian Chy. Co. (120) See Ca. (27) gs.Phone:			. 1]	1 4	\$\$\$\$10.60.\$\$	
	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID and Packing Group (if any))	Number.	10. Containe No.	rs Type	11. Total Quantity	12. Unit WL/Vol.	13. Wa	te Codes
ENERATOR -		 Reg. Folio likeriminal tipineneli. 2 edi.: 6 771777 (Naji) cartarransted oali quip 2000 1972. 2000 il 		Z	Lat	20318	 \[\frac{1}{2} \]	011	
GENE	27 gA 21	2	, , , , , , , , , , , , , , , , , , , ,			·			
		3.							
							;		
	14 Sc	pecial Handling Instructions and Additional Information	· .						
- ₹ }}	-c _e ,	Brolife if at 16 And . West Proper UP: When Handling Materials					z	4204.	19.07
	(3:5): 35 (TOP SELVICE DATE GO-1-17 GENERATOR'S/OFFEROR'S CERTIFICATION: Thereby declare that the cont		116	COMPA			2.79	nd nachaod
	r E	marked and labeled/placarded, and are in all respects in proper condition for the Exporter, I certify that the contents of this consignment comform to the terms of t certify that the waste minimization statement identified in 40 CFR 262.27(a) (if	nsport according to applicable to the attached EPA Acknowledgm	international and nation ent of Consent	nal governmen	ntal regulations.	if export: st	ipment and I am	the Primary
\prod		rators/Offerors Printed/Typed Name. CHADID D. (120WIM AS AUCON For LO	nnar) Signaturg	entelle	03/			Month OF	Day Year
ILL	16. Int	lernational Shipments Import to U.S. sporter signature (for exports only);	Export from U.S.	Port of entr					
	17. Tr	ansporter Acknowledgment of Receipt of Materials porter 1 Printed Typed Name	Signature					Month	Day Year
TRANSPORTER		plonter 2 Printed/Typed Name	Signature					Month	Day Year
TRA	18 O	Scrépancy		· · · · · · · · · · · · · · · · · · ·					<u> </u>
		State of the State	Туре	Residue		Partial Rej	ection		Full Rejection
 <u> </u>	185. A	Alternate Feolity (or Gönerator)		Manifest Reference	Number:	U.S. EPAID N	lumber		
FACILI 1	Facilit	ti/s Phone:				}			
GNATED FACILITY		Signature of Alternate Facility (or Generator)	- 	 	- ,	<u> </u>	······································	Monti	Oay Yes
us	E .	CALLET VICTOR AND	wasta treatment disposal and	(ecvčlino systems)	<u> </u>			 -	
·Ų		azardous Wasta Réport Management Method Codes (i.e., codes for hazardous	3			14			
)]]	1.	2.	3.			4.			
	1. 20. De	azardous Waste Report Management Method Codes (i.e., codes for hazardous 2. esignated Facility Owner or Operator. Certification of receipt of hazardous material Name	3.	xcept as noted in Item	ı 18a	4.		Monti	Day Yea

	NIFORM		1. Generator ID Number	another state	2. Page 1 of	3. Emer	gency Response	Phone		Tracking Nur	7325		
_15		r's Name and Mail	ng Address ! ; ;					(if different t	nan mailing addres		· ~ ~~ ~	<u></u>	
. j.		- (496-Walm Wallere	igt Nov Suide (190). A 124 was		•		77 18 1 9 6 1 8 18 18 18 18 18 18 18 18 18 18 18 18 18	ă.					
		Phone:	65 191 t			1	***************************************						
6.	enerator's Transport	Phone: ter 1 Company Nan	ne ,					·. 	U.S. EPA ID I	Number			17.0
	1	ATE	77 7 1 NA	521 / Hally	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				12,177	15/	V 60		
7.		ter 2 Company Nan	ne						U.S. EPAID N	lumber	·····		7
							,						
.83	Designat	ed Facility Name a	nd Site Address						U.S. EPA(D)	Number			
			kyline froud							1.54	(सम्बद्धाः हेर्		
l l e	acity's Pt		第 574年4月19日。	99 29. +2€1 -					4.				
7			ion (including Proper Shippi	ng Name, Hazard Class, ID N	umber.		10. Contair	ners	11. Total	12. Unit			
		d Packing Group (if	any))	· · · · · · · · · · · · · · · · · · ·			No.	Туре	Quantity	WL/Vol:	13. Was	te Code s	
Į	1	blem bet	k A. Ha, radionis A.	ush budut		İ		:	ાઇણા		151		7.77
ğ	1	e trability o	enthangmak dewilly	1.4.6.1.4.1.3.1.4.1.3.1.1.1.1.1.1.1.1.1.1.1.1			(h)i	4:H	1330	FREF	•		
	2							 	<u> </u>	+ r-c1		-+	
Ы									i i				i A North Co
			<u></u>	. <u></u>				. <u> </u>				1	؛ ذريد در
	3.			, 			<i>:</i>				T	T	1 12
		•	•					1	i ·	1			<u> </u>
╢	4.			<u></u>			• •			+		-1	 ;
	1		·					<u> </u>		1			re like
		<u>,. </u>	gradient state of the state of				i.	<u> </u>				:	ء قديندر <u>يند</u>
		Handling Instruction	ns and Additional Informatio	វា		20	17-01	PEB	12A 2	642	34-19	07	
M		Section 1.	of the When then	lino Nisterio		,	1/1	ga i Tigg			•	·	
1/2			E LATE . LO.	****				by This		•			
1	5 GENE	ERATOR'S/OFFER	OR'S CERTIFICATION: I h	ereby declare that the content	ts of this consignmen	t are fully a	and accurately de	scribed abov	ve by the proper si	hipping name,	and are classifi	ed, packag	ed,
	Expo	rier, I certify that the	contents of this consignme	s in proper condition for trans at conform to the terms of the	attached EPA Ackno	wledamen	t of Consent.	2 .	TANK PART NO. 10	ir export ship	Rueur aug I aw	ine Kilman	у.
		ify that the waste m	the state of the s	ed in 40 CFR 262.27(a) (if l a	m a large quantity ge	nerator) o	r (b) (if I am a sma	all quantity g	enerator) is true:	<u> </u>	Month	Day	Year
	Aich	MEL Dolo	DWIN Asa	gent for le	marli	W	Charle	DE	Luc		106		157
الو		tional Shipments	Import to U.S.		Export from		Port of er	tív/evit	rs <u></u>	Andrew Commencer	10%	(INC BOSTA)	<u>p≠ 2 1 § 1</u> 20 3 20 1
_		er signature (for exp	orts only):	<u> </u>	الالعادة المحاومية فيسبه		Date leav				e diamento de la composición del composición de la composición de la composición de la composición del composición de la composición del		- 18 देव है । अस्तर्भाव (
	~ C WIGC / -	orter Acknowledgme r-1 Printed/Typed N	ent of Receipt of Materials			gnaturé			27 AT 47 AT	e i grafi si A	Month	Day	Year
ANSPOR	, an appare	(1) Printed Typed N	ame		ិ	Anemin.	$a \sim$	1 1) y		•	and and	1/2/	17
왉	ransporte	r 2 Printed/Typed N			S	ignature .	<u> </u>	<u> </u>	en e		Month:	Day	Year
Ĕ		· · · · · · · · · · · · · · · · · · ·	:_	·			83 8			··	<u> </u>		<u> </u>
1 1-	B. Discret										2.00		 ;
	8a. Discre	epancy Indication S	pace Quantity		уре	[Residue		Partial Re	jection		Full Reject	tion
						1.	lanifest Reference	a Niimhari					
⊵ †	8b. Altern	ate Facility (or Gen	erator)		 		-compositions and	o muliatel.	U.S. EPA ID	Number	<u> </u>		
	acility's P		alle des Comment	<u> </u>				<u>.</u>			1 44		V
NATED	oc. Signal	ILITE OF AVIETNATO FA	cility (or Generator)								Month	Day	Year.
	9 Hazan	lous Wasta Room	Management Method Codes	(i.e., codes for hazardous wa	asia treatment disco	al and m	cycling systems)		<u> </u>			<u> </u>	<u>i</u>
1	- meat	AND LIBOR LEDING	2	- from works to received at	3.				4.	······································		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
1	<u> </u>			:			· · · · · · · · · · · · · · · · · · ·						
			r or Operator: Certification o	f receipt of hazardous materia			ept as noted in ite	m 18a	······································		· · · · · · · · · · · · · · · · · · ·	1 -	
	ninted/Typ	ped Name	· · · · · · · · · · · · · · · · · · ·		1	ignature					Monih	Day	Year
I				<u> </u>							ſ	1	F

		1. 6	lite (12-pitch) typewrite		2 Page 1 of	3 Framency Passon	e Phone	4 Manifest	Form A Tracking Nun		3 No. 2050-0039
	IIFORM HAZARDOU WASTE MANIFEST	IS 1. Generatorio	ARBAT MI	:	2.1 age 101	3. Ernergency Respons	or Filance			7324	JJK
6,	Generator's Name and N	lailing Address		<u> </u>		Generalor's Sile Addres	s (il different th				
- \		ताम र्युट्ट नाम	· ithi			WOOLK!					
		- 15 miles			1	Makedshiph, c	-1				
	nerator's Phone:							U.S. EPA ID N	limber		
9.	inasponer roompany	7. 7	41971	I	7	_		1 / 11	C	-5/3	1235
7.	Transporter 2 Company	Name	\$11 m	<u> </u>	13		<u> </u>	U.S. EPAID N			
			•		,			1	•		
8.	Designated Facility Nam	e and Site Address			· -			U.S. EPA ID N	lumber		
		Samuel Constitution (Constitution)							. 33	(利用 取3.5)(14)	
			itte offer kkelstell.	1						1000 marine (1)	
Fa	clity's Phone:	C. P.V.		1	<u> </u>			<u> </u>			
9			er Shipping Name, Hazard	i Class, ID Number		10. Cont		11. Total	12. Unit	13. Was	e Codes
H	M and Packing Grou	b (a suà))				No.	Туре	Quantity	Wt.Vol.		
	frank f	COR'S, Plaziondo	und Winger bedal					22/84		30	
š	र¥ धर्मन ्	િલ્સ્ના ર્સ સામાં માનવ	Ewah I 146 PPN	4.639		(siz!	133	2366	1 2		
Ē.	2			<u> </u>				 	1 3 C 7	- -	- 15 EA
5						1	1				
	3.		· · · · · · · · · · · · · · · · · · ·						1		
		20							l`	 	\$ 000 PM
\prod		· ·		417.				1		1 Marie	. 1. g = 11 - 1. g = 12
	4.		•			1	1.				
	' 						è		1 1		
١Ļ	. Special Handling Instr	refines and Additional	Information	<u> </u>	189 (1997) 1887 - 47 (1997)		<u> </u>		1 1		<u> </u>
)	Strate States of the Strate St	and (524)				\sim 2	007-1	of PCB	RA 2	1A 204	19.07
	4 5 4 4 6 4	No. 454	r Handling Make	ind		•	iki lih	a			
	U 6 4.6.	MEE INST	E : 61 07				Site Hill	-B116			
	. GENERATOR'E/OF	FEROR'S CERTIFICAT	ION: I horeby declare the	at the contents of this	consignment	are fully and accurately	described abo	ve by the proper si	nipp in g name,	and are classifie	d, packaged,
			It respects in proper condi- insignment conform to the				ational govern	mental regulations	. Il export ship	oment and I am 1	he Primary
11	I certify that the was	e minimization stateme	ent identified in 40 CFR 26				mail quantity g	enerator) is trúe.			N
	enerator's/Offeror's Prin		An	10 /40	Sign	nature	1 1			Month	Day Year
W	MICHAPL	1) . (+01)1.11	J(A) Again				1.1	35//-	de de la companya de La companya de la co	100	11\$107
	i: International Shipmen	C Impor	two U.S.	بيا.	Export from		entry/exit:				<u></u>
	ransporter signature (for Transporter Acknowled		sterials.			Date le	aving U.S.:		ing read to the contract of th	- W - 275 5 - 125 5	
밝	ansporter 1 Printed/Type				Ski	nature	7			Month	Day Year
ᇎ	Albert	Bunka	,,, T, _			Mic II	land la	with .		16.7	14117
ž T	ansporter 2 Printed/Typ	ed Name			Sig	nature		1		Month	Day Year
ᄠ	-		b		<u> l</u>						
7 -	3. Discrepancy		· · · · · · · · · · · · · · · · · · ·	. A. Suran	· · · · · · · · · · · · · · · · · · ·					· · · · · · · · · · · · · · · · · · ·	
	Sa. Discrepancy Indicati	on Space O	uantity	Type		Residue		Partial Re	jection		Full Rejection
11					_	gaskinini wa wa wa	<u>Linguis de 80</u>				· =
⊤اح	b. Alternate Facility (or	Generator)				Manifest Refere	nce Number:	U.S. EPAID	Númber	- <u>\$ 100</u> - 191.	te de la constitución de la cons
핅		, -							•		•
E F	acility's Phone:							T			<u></u>
GNATED FACILITY	Bc. Signature of Alternat	e Facility (or Generator)	· · · · · · · · · · · · · · · · · · ·	······································	· · · · · · · · · · · · · · · · · · ·				Month	Day Year
žL					<u> </u>	4		tion of the same	<u> </u>		
ধ্য	9. Hazardous Waste Re	port Management Meth	od Codes (i.e., codes for I	hazardous waste tree	stment, dispos	al, and recycling system	s)				
1	r.	•	2.		3.			4.			
11	ng katalan da ta				1	(A)	garagas and a	<u> </u>		·	<u> </u>
	Designated Facility O Inted/Typed Name	wner or Operator: Certi	fication of receipt of hazar	roous materials cover		ilest except as noted in pnature	Item 18a	<u>. </u>	 ,	Month	Day Year
\prod^{r}	- contract Abirn capitals				١	2				inchin:	1
EPA F	omi 8700-22 (Rev. 3	05) Previous editio	ns are obsolete						AF-19-	1	1 1
() (and aloner liver o	ANTO LEADING COUNTY	···· ale éraniere.						GENERA	ATOR'S IN	ITIAL COPY

lac	se print or type. (Form designed for use on still (12-pitch) typewriter.)	206				Form	a Annowed	OMB No	. 2050-0039
	UNIFORM HAZARDOUS 1. Generator ID Number CAR 000123117	2. Page 1 of	3, Emergency Response 1 1-800-838-1477	Phone	4. Manifest 1	racking N			JK
	Signerator's Name and Mailing Address Length Mure Inhand LLC 690 Wahruit Ave. State 100 Vallejo, CA 94592 Generator's Phone: 707, 747-4800	MARING:	Senerator's Site Address (i Lemman Mance Islen IRO9 / IR12 Mare Island, C.A	nd LLC	mailing address	s)	· ·		
	6 Transporter 1 Company Name				U.S. EPAID N	201	ンウバ	18	809
	7. Transporter 2 Company Name 6. Designated Facility Name and Site Address			£	U.S. EPAID N		*	,	
	Chomical Waste Management 35251 Old Skyline Road Kettleman City, CA 93239 559-386-9711		1 !		U.S. EFFAILIN		T000646	117	
	9a. 9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID N and Packing Group (If arry))	lumber,	10. Containe No.	ers Type	11. Total Quantity	12. Unit Wu/Vol.	13.	Waste Cod	es
RATOR	1. RQ, Potychlorinated Biphenyls, Solids, 9 UN231 (Soil contaminated with up to 860 PPM Arochlo		100	DT.	21718	Kg.	611.	261	,
SEME	2.	-							i i i i i i i i i i i i i i i i i i i
	3.	<u> </u>							7
	· · · · · · · · · · · · · · · · · · ·								
					*				
	Profile #: a) EC7635 Profile #: a) EC7635 Wear Proper PPE When Handling Material OJF OF SECVICE DATE・ ロー・0子 15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby dedare that the contemparted and labeled/plecarded, and are in all respects in proper condition for trans Exporter, I certify that the contents of this consignment conform to the terms of the	ts of this consignment a port according to applic attached EPA Acknowle	re fully and accurately dea able international and natio adgment of Consent.	cribed above t nal governme	by the proper shi ntal regulations.	pping nam	e, and are cla	seified, pac	kaged.
	I contify that the waste minimization statement identified in 40 CFR 262:27(a) (if I a Generator's Offeror's Printed/Typed Name MICHEALD GODWN ARK AGUS Cor 16. International Shipments Import to U.S.	Laprace Quantity general Sign Sign Export from U	Michael	08	rator) is true.	, , , , , , , , , , , , , , , , , , ,	Mo D	nth Da	407
E 2 4	Transporter signature (for exports only): 17. Transporter Acknowledgment of Receipt of Materials		Date leavin			·.		<u></u>	
TIKANSPORT	Transporter 1 Printed/Typed Name Transporter 2 Printed/Typed Name		Anna CON	9	600	Ln:	Mor Mor	od I	407
	18. Discrepancy Indication Space Quantity	уре	Rásidue Menifest Reference	Number:	Partial Rek	× °	*	Full Re	ijection
TEACH.ITY	18b. Alternate Facility (or Generator) Facility's Phone:				U.S. EPAID N	umber		· ——	
JONATED	Signature of Alternate Facility (or Generator) Hazardous Wasta Report Management Method Codes (i.e., codes for hazardous wastangement Method Codes (i.e., codes for hazardous wastange	aste treatment, disposal	and recycling systems)	-			M	onth Da	By: Year.
	4132 2	3.			4.	, acc			
	20. Designated Facility Owner of Operator: Certification of receipt of hazardous material Printed Typed Name.		est except as noted in Item nature	18a .	A	برين مورين نيم كم	Mi ال دري	onth Da	y Year
EP/	Form 8700-22 (Rev. 3-05) Previous editions are obsolete.	orași de la companii	مسب	/ D	ESIGNAT	ED FAC	II ITY T	O GEN	ERATOR

as	e print	t or type. (Form designe					·		-			Approved. (DMB No. 2	050-0039	
۱	WA	STE MANIFEST		ber CAR000123117	, ²	2. Page 1 of	1-800-83	8-1477	,		239	732	3 Ju	IK	
ı M	۱۱حر	erator's Name and Mailing A F 690 Walnut Vallejo, CA ator's Phone: 707 50	Ave. Suite 1 94592	00	ומן	AJL ING	Cenerator's Ste IRO9 / IR Mare Isla	.12		an mailing address	3)				
	6. Tran	sporter 1 Company Name	000	+dons						U.S. EPAID NO U.S. EPAID NO	200	0182	1,45	/	
		gnaled Facility Name and S Actinical Was 35251 Old Sky Kettleman Cit /s Phone:	line Road		1	1			1 A	U.S. EPA ID N	-	2 (1000646)	117		
	9a. HM	9b. U.S. DOT Description and Packing Group (if any		hipping Name, Hazard	Class, ID Number.			0. Contair lo.	ers Type	11. Total 12. Unit Quantity W1./Vol.		13. V	13. Weste Codes		
KAIO	,	(Debris cor		Waste Solid 7th 4.430 PPM	(PCB)		.1	001	m	20545	Ϋ́g	261			
F		2									Ű				
	1	4.		<u></u>					·						
	•	ecial Handling Instructions	A A A A A A A A A A A A A A A A A A A	mation										**	
) 15. (Profile # a) E Wear Proper I	C5231 PE When F S CERTIFICATION ad, and are in all re intents of this consi	iandling Mater - 06-14-07 It thereby declare that spects in proper conditionment conform to the	the contents of this ion for transport acco terms of the attached	consignment rding to appl	icable internation wiedgment of Cor	urately de al and nati isent.	sorbed above onal government	nental regulations.	pping name	e, and are clas	sified, pack	aged;	
IN THE	16. Int	ator's/Offeror's Printed/Type ICHAEL Dw Iernational Shipments porter signature (for export	Dimport to	As agent		Ar)	u.s.	Port of en	try/exit:			Mon I Q	1 1	489	
THEMNSPORTER	17. Transp	ansporter Acknowledgment oporter 1 Painted/Typed Nam Tom Form F	of Receipt of Materi Heco	ls			gnature 10,~~1 gnature	R				Mon Mon	143	Year 107 Year	
		screpancy indication Spac	e Duan	ày >	Турв	· *	* 19	sidue Referenci	: e Number:	Pertial Rej	**	[Full Rej	ection	
THEORY	Facet	Nternate Facility (or Genera ly's Phone:								U.S. EPA ID N	lumber				
JONATE		Signature of Alternate Facilit azardous Waste Report Ma		Codes (i.e., codes for h	azardous wașle treat	ment, dispos	sel, and recycling	systems)	·			Mo	nth Dar	y Year	
	20.0	esignated Facility Owner or	Onerstor Certifice	ing of receipt of horses	louis materials course	3.	nifest except ac	cted in the	m 18a	4.					
↓ EP/	Printe	adTyped Name	·	The same	THE STREET COVERE		ignature	ACCI AT HO		2	- , 200 y .	Mo	$\frac{1}{2}$	4/1-	
ď	, we (4)		· · · · · · · · · · · · · · · · · · ·							DESIGNAT	⊷I) FΔ(THE PERSON	HAMME	-RATOR	

. 7.